

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8001020279 DOC DATE: 79/12/26 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH.NAME AUTHOR AFFILIATION
 SHALLER,D.V. Indiana & Michigan Electric Co.
 RECIP.NAME RECIPIENT AFFILIATION
 KEPPLER,J.G. Region 3, Chicago, Office of the Director

SUBJECT: ~~BO~~ on 791224 re IE Bulletin 79-14. Indication that under
 condition of design basis earthquake, duct work on trains of
 containment air recirculation sys would be stressed beyond
 yield. Followup rept to be sent by 800107.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Incident Reports

NOTES: I & E - 3 Cys ALL MATL.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR
	05 BC <u>OR8 & 1</u>	4	4			
INTERNAL:	01 <u>REG FILE</u>	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACIDENT ANLYS	1	1
	29 AUX SYS BR	1	1	E JORDAN/IE	1	1
	HANAUER, S.	1	1	R IRELAND	3	3
	STS GROUP LEADR	1	1	TMI-H STREET	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

JAN 3 1980

JAN 3 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR

54

51 ENCL

0

60
402

00: 6. 11. 19.



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

December 26, 1979

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm our telephone report to your Mr. John Riceland, Staff Duty Officer - Washington Office, on December 24, 1979, at 1650 hours.

At that time we reported that word was received from our New York Office relative to IE Bulletin 79-14 that indicated that under the condition of the design basis earthquake, the duct work on both trains of the Containment Air Recirculation System would be stressed beyond yield. Immediate action was taken by the writer to bring the Unit to Cold Shutdown.

A followup report will be submitted by January 7, 1980, as required by Technical Specification Section 6.9.1.8.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.S. Hunter
R.W. Jurgensen
R.F. Kroeger
R.W. Kilburn
R.E. Masse, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.

G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

A002
S
1/0

8001020

279