

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8001070397 DOC. DATE: 79/12/26 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH. NAME AUTHOR AFFILIATION
 SHALLAR, D.V. Indiana & Michigan Power Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: ~~800107~~ 791224, util reported that under condition of DBE, duct work on both trains of containment air recirculation sys should be stressed beyond yield. Followup rept completed by 800107.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Incident Reports

NOTES: I & E - 3 CYS ALL MATL.

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	05 BC ORB #1	4		
INTERNAL:	01 REG FILE	1	02 NRC PDR	1
	09 I&E	2	11 MPA	3
	14 TA/EDO	1	15 NOVAK/KNIEL	1
	16 EEB	1	17 AD FOR ENGR	1
	18 PLANT SYS BR	1	19 I&C SYS BR	1
	20 AD PLANT SYS	1	22 REAC SAFT BR	1
	23 ENGR BR	1	24 KREGER	1
	25 PWR SYS BR	1	26 AD/SITE ANAL	1
	27 OPERA LIC BR	1	28 ACDENT ANLYS	1
	29 AUX SYS BR	1	E JORDAN/IE	1
	HANAUER, S.	1	R IRELAND	3
	STS GROUP LEADR	1	TMI-H STREET	1
EXTERNAL:	03 LPDR	1	04 NSIC	1
	29 ACRS	16		

JAN 8 1980

AOI
2

60

TOTAL NUMBER OF COPIES REQUIRED: LTR

54

51 ENCL

0



100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

December 26, 1979

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm our telephone report to your Mr. John Riceland, Staff Duty Officer - Washington Office, on December 24, 1979, at 1650 hours.

At that time we reported that word was received from our New York Office relative to IE Bulletin 79-14 that indicated that under the condition of the design basis earthquake, the duct work on both trains of the Containment Air Recirculation System would be stressed beyond yield. Immediate action was taken by the writer to bring the Unit to Cold Shutdown.

A followup report will be submitted by January 7, 1980, as required by Technical Specification Section 6.9.1.8.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.S. Hunter
R.W. Jurgensen
R.F. Kroeger
R.W. Kilburn
R.E. Masse, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.

G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

A002
5/10

DEC 28 1979

8001070

397

W