

REGULATORY INFORMATION DISTRIBUTION SYSTEM (IDS)

ACCESSION NBR:8003210360 DOC DATE: 80/03/17 NOTARIZED: NO DOCKET #  
 FACIL:50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
 AUTH.NAME AUTHOR AFFILIATION  
 WIZNER,D.G. Indiana & Michigan Electric Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 Region 3, Chicago, Office of the Director

SUBJECT: LER 80-010/03L-0: on 800317, during surveillance test, suction valve VMO-102 for containment equalization fan HV-CEQ-2 failed to open, making air recirculation sys inoperable. Caused by maladjusted torque switch in motor operator.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1  
 TITLE: Incident Reports

NOTES: SEND 3 CYS ALL MATL TO I&E.

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	05 BC ORB #1	4	4			
INTERNAL:	00 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACIDENT ANALYS	1	1
	29 AUX SYS BR	1	1	AD/ORP-DOR	1	1
	AEOD	1	1	DOUG MAY-TERA	1	1
	HANAUER, S.	1	1	IRELAND, R.	3	3
	JORDAN, E./IE	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

MAR 24 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR 55 ENCL 52

60

1 11 1 1

2700 2000 1000 500 250 125 62 31 15 7 3 1

10 880

27

27