

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8006240476 DOC.DATE: 80/06/19 NOTARIZED: NO DOCKET #
 FACIL:50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH.NAME AUTHOR AFFILIATION
 LEASE.R.S. Indiana & Michigan Electric Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: LER 80-024/03L-0;on 80520,w/turbine drive auxiliary
 feedwater pump in nonrunning standby position,alarm received
 that pump tripped.Caused by control linkage disconnecting
 from throttle valve.Actual cause could not be determined.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 171
 TITLE: Incident Reports

NOTES: 3cy ALL MAT TO I&E

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	BC <u>VARGA, J.</u> 05	1	1	PM <u>MINER, S.</u> 06	3	3
INTERNAL:	A/D CORE & CS	1	1	A/D RAD PROT	1	1
	A/D REACT SYS	1	1	A/D TECHNOLOGY	1	1
	AEOD	10	10	AUX SYS BR	1	1
	CHEM ENG BR	1	1	CONT SYS BR	1	1
	CORE PERF BR	1	1	EMERG PREP	1	1
	EQUIP QUAL BR	1	1	HANAUER, S.	1	1
	I&C SYS BR	1	1	I&E 09	2	2
	JORDAN, E./IE	1	1	MOORE, V.	1	1
	MPA 11	3	3	NRC PDR 02	1	1
	OP EX EVAL BR	3	3	OR ASSESS BR	1	1
	PPAS	1	1	QA BR	1	1
	<u>REG FILE</u> 01	1	1	SIT ANAL BR	1	1
	SYS INTERAC BR	1	1	TERA:DOUG MAY	1	1
EXTERNAL:	ACRS	16	16	LPDR 03	1	1
	NSIC 04	1	1			

JUN 25 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR

65 65 62 ENCL 62

ADK
4

GD

