

INDIANA & MICHIGAN ELECTRIC COMPANY

P. O. BOX 18
BOWLING GREEN STATION
NEW YORK, N. Y. 10004

July 8, 1980
AEP:NRC:00435

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74

Mr. James G. Keppler, Regional Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137


Dear Mr. Keppler:

This letter provides the required response to the Notice of Violation transmitted to us in Mr. A. B. Davis' letter of June 10, 1980, which we received on June 12, 1980.

This inspection report identifies three (3) shipments from the Donald C. Cook site as having no placard on the front box, in non-compliance with 49 CFR 172.504.

In order to prevent further placard location problems, procedures now require boxes larger than 640 cubic feet in volume to have placards applied on each side and each end. Placards are also required on both cargo box and at the front of the truck-tractor. In addition, the driver of the carrier vehicle is given extra placards to affix in the event that a placard is lost or if the color and/or visibility of the placard becomes substantially reduced.

Very truly yours,


R. S. Hunter
Vice President

RSH/emc

cc: R. C. Callen
G. Charnoff
John E. Dolan
D. V. Shaller - Bridgman
R. W. Jurgensen

JUL 11 1980

8009020232

