

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8206210251 DOC. DATE: 82/06/14 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 HUNTER, R.S. Indiana & Michigan Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director


SUBJECT: Corrects util 820504 ltr which responded to NRC 820430 request for addl info re fire protection - App R compliance.

DISTRIBUTION CODE: A006S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Fire Protection Information (After Issuance of OP. Lic.)

NOTES:

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL
	ORB #1 BC	01	3	3			
INTERNAL:	ELD/HDS3		1	0	IE FILE	06	1 1
	NRR FIORAVANT07		2	2	NRR WAMBACH		1 0
	NRR/DE/CEB 09		2	2	NRR/DL DIR		1 1
	<u>REG FILE</u> 04		1	1	RGN3		1 1
EXTERNAL:	ACRS	11	3	3	LPDR	03	2 2
	NRC PDR	02	1	1	NSIC	05	1 1
	NTIS		1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 21 ENCL 19



INDIANA & MICHIGAN ELECTRIC COMPANY

P. O. BOX 18
BOWLING GREEN STATION
NEW YORK, N. Y. 10004

June 14, 1982
AEP:NRC:0692

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74
FIRE PROTECTION - APPENDIX R COMPLIANCE

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Denton:

In our May 4, 1982 letter to you we stated that we would review that letter in accordance with our Corporate Procedures and inform the NRC if any modifications to it were required. This temporary waiver of our procedural requirements was needed to provide the NRC with the information requested at our April 30, 1982 meeting as expeditiously as possible. Upon review of the letter we would like to inform you of the following:

In Attachment 1:

Item 7 - stated, in part: "To facilitate performing breaker modifications in close proximity to energized circuits, we have, on an interim basis, established around-the-clock, seven-day-week coverage by two qualified electricians/technicians---."

Upon review of the schedule for this coverage, we found that there was a lack of coverage on Saturday and Sunday for a 30 minute period from 2330 to 2400 hours. The coverage schedule was revised on May 21, 1982 to correct this error.

Item 9 - stated, in part: "All licensed operators received formal training in the emergency shutdown procedure during January 1982 requalification training."

A review of the training records for the 38 licensed operators indicated that two (2) operators had not received this training in January 1982 since they were not available at that time. All licensed operators, with the exception of one (1) who is currently off-shift, were trained in the emergency shutdown procedure by June 4, 1982.

A006

1942
1943

1. The first of the two main points of the report is that the Government has failed to do enough to help the people who are in need of help.

2. The second point is that the Government has failed to do enough to help the people who are in need of help.

3. The third point is that the Government has failed to do enough to help the people who are in need of help.

4. The fourth point is that the Government has failed to do enough to help the people who are in need of help.

5. The fifth point is that the Government has failed to do enough to help the people who are in need of help.

6. The sixth point is that the Government has failed to do enough to help the people who are in need of help.

7. The seventh point is that the Government has failed to do enough to help the people who are in need of help.

8. The eighth point is that the Government has failed to do enough to help the people who are in need of help.

9. The ninth point is that the Government has failed to do enough to help the people who are in need of help.

Item 10 - stated: "The two electricians/technicians presently on shift on a 24 hour-per-day, seven-day-week schedule have received training in the breaker modification procedure."

The coverage from 0001 to 0700 hours was provided by one (1) Indiana & Michigan Electric Company Supervisor and one (1) contractor electrician. We identified that the contractor electricians assigned to this coverage had not received training in the breaker modification procedure. These electricians were properly trained on May 21, 1982.

In Attachment 3:


Page 2 of 2, Paragraph 1 - stated in part: "We believe the hole in the oil lift enclosure is for a flexible conduit to the oil lift pump motor of the spare RCP Motor".

Since then we have had the opportunity (due to a Unit outage) to examine the oil collection enclosures in Unit 1. We found that the conduit hole exists on the "in-service" RCP motor oil life pump enclosures. This hole was repaired prior to bringing Unit 1 back on line. The senior Resident Inspector was advised of this action.

We regret any inconvenience this may have caused you.

This document has been prepared following Corporate procedures which incorporate a reasonable set of controls to insure its accuracy and completeness prior to signature by the undersigned.

Very truly yours,



R. S. Hunter
Vice President

RSH/os

cc: John E. Dolan - Columbus
R. W. Jurgensen
W. G. Smith, Jr. - Bridgman
R. C. Callen
G. Charnoff
Joe Williams, Jr.
NRC Resident Inspector at Cook Plant - Bridgman

1. The first of these is the fact that the
of a "..." in the
in the first of these...

(1) The second of these is the fact that the
of a "..." in the
in the first of these...

2. The third of these is the fact that the

of a "..." in the
in the first of these...

3. The fourth of these is the fact that the
of a "..." in the
in the first of these...

4. The fifth of these is the fact that the

5. The sixth of these is the fact that the
of a "..." in the
in the first of these...

6. The seventh of these is the fact that the

7. The eighth of these is the fact that the

8. The ninth of these is the fact that the
of a "..." in the
in the first of these...