

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8412180520 DOC. DATE: 84/12/13 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME: AUTHOR AFFILIATION
 ALEXICH, M. P. Indiana & Michigan Electric Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director

SUBJECT: Informs of progress in achieving compliance w/10CFR50, App R.
 Recent insp identified pipe tunnel in auxiliary bldg which
 communicates w/other fire areas. Const of door opening will
 take 3 months. Conditions will be resolved by 850331.

DISTRIBUTION CODE: A006D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: Fire Protection

NOTES: 05000315
 OL: 10/25/74
 OL: 12/23/72 05000316

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL
	NRR ORB1 BC 01		3				
INTERNAL:	ACRS 11		3		ADM/LFMB		1 0
	ELD/HDS3		1		IE FILE 06		1 1
	IE/WHITNEY, L		1		NRR FIORAVANT07		2 2
	NRR WAMBACH		1		NRR/DE/CEB 09		2 2
	NRR/DL DIR		1		REG FILE 04		1 1
	RGN3		1				
EXTERNAL:	LPDR 03		2		NRC PDR 02		1 1
	NSIC 05		1		NTIS		1 1

INDIANA & MICHIGAN ELECTRIC COMPANY

P.O. BOX 16631
COLUMBUS, OHIO 43216

December 13, 1984

AEP:NRC:0692W

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74
INFORMATION CONCERNING D. C. COOK NUCLEAR PLANT
STATUS WITH REQUIREMENTS OF APPENDIX R TO 10 CFR 50

Mr. Harold R. Denton, Director
Office Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Denton:

In previous correspondence we have committed to perform certain actions in order to bring the D. C. Cook Nuclear Plant into compliance with 10 CFR 50 Appendix R. This letter is submitted to keep you informed of circumstances which affect our progress towards achieving the Appendix R compliance goal.

During a recent Plant inspection by EPM, our consultant, an inspector identified a pipe tunnel in the auxiliary building which had not been previously evaluated. In the process of evaluating the pipe tunnel we have determined that it does communicate with other fire areas via a door opening, wall penetrations (pipe), and floor/ceiling hatches.

It will take approximately 3 months to have a door fabricated for the above opening because it is an unusual size. We expect to have the above conditions resolved by March 31, 1985. We will include the affected areas in our daily fire inspection program in order that the Plant may continue to operate safely.

This document has been prepared following Corporate procedures which incorporate a reasonable set of controls to insure its accuracy and completeness prior to signature by the undersigned.

8412180520 841213
PDR ADDCK 05000315
F PDR

Very truly yours,

M. P. Alexich 12/13/84
M. P. Alexich
Vice President

MPA/cm

cc: John E. Dolan
W. G. Smith, Jr. - Bridgman
R. C. Callen
G. Bruchmann
G. Charnoff
NRC Resident Inspector - Bridgman

A006
1/0

