

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8706030036 DOC. DATE: 87/05/26 NOTARIZED: NO DOCKET #
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 SMITH, W. G. Indiana & Michigan Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DAVIS, A. B. Document Control Branch (Document Control Desk)

SUBJECT: RO: on 870526, fire suppression water sys not operable per
 Tedh Spec 3.7.9.1.b. Caused by planned isolation of east leg
 of fire protection ring header for new const. Const will be
 completed by 870630.

DISTRIBUTION CODE: A006D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR/Licensing Submittal: Fire Protection

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-3 LA	1 0	PD3-3 PD	5 5
	WIGGINGTON, D	1 1		
INTERNAL:	ARM/DAF/LFMB	1 0	NRR WERMEIL, J	1 0
	NRR WHITNEY, L	1 1	NRR/DEST/ADS	1 1
	NRR/DEST/PSB	1 1	OGC/HDS1	1 0
	<u>REG FILE</u> 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 17 ENCL 13

THE SECRETARY OF THE INTERIOR
WASHINGTON, D. C. 20540
BUREAU OF LAND MANAGEMENT
PO BOX 168
DENVER, CO 80201
TELEPHONE (303) 733-8000
FAX (303) 733-8001

FOR INFORMATION OF THE BUREAU OF LAND MANAGEMENT, THE FOLLOWING INFORMATION IS BEING FURNISHED TO YOU FOR YOUR INFORMATION AND USE:

1. NAME OF THE LAND: [illegible]
2. LOCATION OF THE LAND: [illegible]

DATE	DESCRIPTION	AMOUNT	REMARKS
1/1/80	Acquired	100.00	Initial purchase
2/1/80	Acquired	200.00	Second purchase
3/1/80	Acquired	300.00	Third purchase
4/1/80	Acquired	400.00	Fourth purchase
5/1/80	Acquired	500.00	Fifth purchase
6/1/80	Acquired	600.00	Sixth purchase
7/1/80	Acquired	700.00	Seventh purchase
8/1/80	Acquired	800.00	Eighth purchase
9/1/80	Acquired	900.00	Ninth purchase
10/1/80	Acquired	1000.00	Tenth purchase



INDIANA & MICHIGAN ELECTRIC COMPANY

Donald C. Cook Nuclear Plant
P.O. Box 458, Bridgman, Michigan 49106

May 26, 1987

Donald C. Cook Nuclear Plant unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attn: A. B. Davis

Dear Mr. Davis:

This is to confirm a verbal report made to the NRC Operations Center via the Emergency Notification System at 1006 hours on May 26, 1987. At that time the NRC Operations Center was informed that the Fire Suppression Water System was not operable as required by Technical Specification 3.7.9.1.b due to the planned isolation of a portion of the east leg of the outside fire protection ring header. This isolation was required to facilitate rerouting of the cross tie between the ring header and the Auxiliary Building Fire Protection Systems. This relocation was necessitated due to new construction in this area. The relocation of the Fire Protection cross tie piping is expected to be completed within thirty days and the Fire Protection System returned to service by June 30, 1987.

No safety related Fire Protection Systems were removed from service due to the isolation of this section of Fire Protection piping. Backup fire protection is available from nearby fire hydrants.

This letter will fulfill the requirements of Technical Specification 3.7.9.1 action b.2b which requires a follow up report within twenty-four hours of the telephone call to the Emergency Notification Center and Technical Specification 3.7.9.1 action b.2c that requires a follow up report within fourteen days.

Respectfully,

W. G. Smith, Jr.
Plant Manager

/krb

cc: See Attached Distribution List

8706030036 870526
PDR ADOCK 05000315
S PDR

Acob
1/0

John E. Dolan
A. B. Davis, Region III
M. P. Alexich
R. F. Kroeger
H. B. Brugger
R. W. Jurgensen
NRC Resident Inspector
R. C. Callen
G. Charnoff, Esq.
D. Hahn
INPO
PNSRC
A. A. Blind
Dottie Sherman, ANI Library
D. Wigginton, NRC