

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8711130299 DOC. DATE: 87/11/10 NOTARIZED: NO DOCKET #
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 ALEXICH, M. P. Indiana Michigan Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 MURLEY, T. E. Document Control Branch (Document Control Desk)

SUBJECT: Discusses extension to test unit motor operated valves in accordance w/IE Bulletin 85-03 per 871104 telcon. Extension effective as of 871115. Refueling outage rescheduled for approx May-Jun 1988 per 860516 request.

DISTRIBUTION CODE: IE11D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Bulletin Response (50 DKT)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-3 LA	1	PD3-3 PD	1
	WIGGINGTON, D	1		
INTERNAL:	AEOD/DOA	1	AEOD/DSP	1
	AEOD/DSP/TPAB	1	NRR/DEST/ADE	1
	NRR/DEST/ADS	1	NRR/DEST/MEB	1
	NRR/DOEA/EAB	1	NRR/DOEA/GCB	1
	NRR/DRER/EPB	1	NRR/PMAS/ILRB	1
	<u>REG FILE</u> 02	1	RES/DE/EIB	1
	RGN3 FILE 01	1		
EXTERNAL:	LPDR	1	NRC PDR	1
	NSIC	1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 19 ENCL 0

Indiana Michigan
Power Company
One Summit Square
P.O. Box 60
Fort Wayne, IN 46801
219 425 2111



AEP:NRC:0966D

Donald C. Cook Nuclear Plant Unit No. 2
Docket No. 50-316
License No. DPR-74
RESPONSE TO IE BULLETIN NO. 85-03

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Attn: T. E. Murley

November 10, 1987

Dear Dr. Murley:

Based on our conversation with Mr. M. Phillips, NRC Region III, on November 4, 1987, we understand that an extension to test D. C. Cook Unit 2 motor-operated valves in accordance with IE Bulletin 85-03 will be effective as of November 15, 1987, unless we are informed otherwise. Bulletin 85-03 concerns "Motor-Operated Valve Common Mode Failures During Transients Due To Improper Switch Settings." We understand that the extension is effective until 1988 refueling occurs.

In our letter AEP:NRC:0966, dated May 16, 1986, we requested an extension until the Unit 2 refueling outage, which was then scheduled for February, 1988. The Unit 2 refueling outage is now scheduled for approximately May-June 1988.

This document has been prepared following Corporate procedures which incorporate a reasonable set of controls to ensure its accuracy and completeness prior to signature by the undersigned.

Sincerely,

A handwritten signature in cursive script, appearing to read "M. P. Alexich".

M. P. Alexich
Vice President
cm

8711130299 871110
PDR ADOCK 05000316
Q PDR

cc: John E. Dolan
W. G. Smith, Jr. - Bridgman
R. C. Callen
G. Bruchmann
G. Charnoff
NRC Resident Inspector - Bridgman
A. B. Davis - Region III

IE 11
1/0