

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8911090278 DOC.DATE: 89/10/30 NOTARIZED: NO DOCKET #  
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
 AUTH.NAME AUTHOR AFFILIATION  
 BLIND,A.A. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP.NAME RECIPIENT AFFILIATION  
 DAVIS,A.B. Document Control Branch (Document Control Desk)

SUBJECT: RO:on 891030,fire suppression water sys not operable,per  
 Tech Spec 3.7.9.1b.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 2  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1	PD3-1 PD	1
	GIITTER,J.	1		
INTERNAL:	ACRS MICHELSON	1	ACRS MOELLER	2
	ACRS WYLIE	1	AEOD/DOA	1
	AEOD/DSP/TPAB	1	AEOD/ROAB/DSP	2
	DEDRO	1	NRR/DEST/ESB 8D	1
	NRR/DEST/ICSB 7	1	NRR/DEST/MEB 9H	1
	NRR/DEST/MTB 9H	1	NRR/DEST/PSB 8D	1
	NRR/DEST/RSB 8E	1	NRR/DEST/SGB 8D	1
	NRR/DLPQ/HFB 10	1	NRR/DLPQ/PEB 10	1
	NRR/DOEA/EAB 11	1	NRR/DREP/RPB 10	2
	NUDOCS-ABSTRACT	1	<del>REG FILE 02</del>	1
	RES/DSIR/EIB	1	RGN3 FILE 01	1
EXTERNAL:	EG&G WILLIAMS,S	4	L ST LOBBY WARD	1
	LPDR	1	NRC PDR	1
	NSIC MAYS,G	1	NSIC MURPHY,G.A	1
	NUDOCS FULL TXT	1		

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 38 ENCL ~~38~~ 0

Indiana Michigan  
Power Company  
Cook Nuclear Plant  
P.O. Box 458  
Bridgman, MI 49106  
616 465 5901



October 30, 1989

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2  
Docket Nos. 50-315 and 50-316  
License Nos. DPR-58 and DPR-74

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Attn: A. B. Davis

Dear Mr. Davis:

This is to confirm a verbal report made to Mr. E. Schweibinz of your staff at 1430 hours on October 30, 1989. At that time Mr. Schweibinz was informed that the Fire Suppression Water System was not operable as required by Technical Specification 3.7.9.1b due to the isolation of a portion of the East leg of the outside fire protection ring header. This isolation was necessitated to allow replacement of a ringheader valve.

One fire hydrant in the protected area was removed from service as a result of this isolation. Backup fire protection is available from nearby fire hydrants and the Plant fire truck. The fire header is expected to be returned to service by November 3, 1989.

This letter fulfills the requirements of Technical Specification 3.7.9.1, Action b.2b, which requires a followup report no later than the next working day following the impairment, and Technical Specification 3.7.9.1, Action b.2c, that requires a followup report within 14 days.

Respectfully,

A. Alan Blind  
Plant Manager

c: See Distribution List

8911090278 891030  
PDR ADOCK 05000315  
PDC

FE22

c: D.H. Williams, Jr.  
A.B. Davis, Region III  
M.P. Alexich  
P.A. Barrett  
J.E. Borggren  
R.F. Kroeger  
NRC Resident Inspector  
J.G. Giitter, NRC  
R.C. Callen  
G. Charnoff, Esq.  
Dottie Sherman, ANI Library  
D. Hahn  
INPO PNSRC  
A.A. Blind  
S.J. Brewer/B.P. Lauzau