

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9903050362 DOC.DATE: 99/02/24 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH.NAME AUTHOR AFFILIATION
SAMPSON,J.R. American Electric Power Co., Inc.
RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-003-00 re CR pressurization sys surveillance
test not testing sys in normal operating condition.
Commitments made by util, listed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2 + 4
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
	PD3-3 PD		1	1	STANG, J		1	1
INTERNAL:	AEOD/SPD/RAB		2	2	AEOD/SPD/RRAB		1	1
	FILE CENTER		1	1	NRR/DRCH/HOHB		1	1
	NRR/DRCH/HQMB		1	1	NRR/DRPM/PECB		1	1
	NRR/DSSA/SPLB		1	1	RES/DET/EIB		1	1
	RGN3 FILE 01		1	1				
EXTERNAL:	L ST LOBBY WARD		1	1	LMITCO MARSHALL		1	1
	NOAC POORE, W.		1	1	NOAC QUEENER, DS		1	1
	NRC PDR		1	1	NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

NOTE TO ADD: KIDS RECEIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 18

American Electric
Cook Nuclear Plant
One Cook Place
Bridgman, MI 49106
616 465 5901



February 24, 1999

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/99-003-00, "Control Room Pressurization System Surveillance Test Does Not Test System in Normal Operating Condition."

The following commitment has been identified:

- The root cause for this event has not been completed. Also, the control room habitability analysis is currently in progress. Based on the results of these analyses, additional corrective actions, including preventive actions may be developed. It is anticipated that, if significant changes are identified, supplemental information regarding corrective and preventive actions will be provided in an update to this LER by July 30, 1999.

Sincerely,

A handwritten signature in cursive script that reads 'John R. Sampson'.

J. R. Sampson
Site Vice President

/mbd
Attachment

9903050362 990224
PDR ADCK 05000315
S PDR

11
IL 2

c: J. E. Dyer, Region III
R. P. Powers
P. A. Barrett
D. F. Kunsemiller
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector