

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9903260063 DOC.DATE: 99/03/18 NOTARIZED: NO DOCKET #  
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315  
 AUTH.NAME: AUTHOR AFFILIATION  
 POWERS,R.P. Indiana Michigan Power Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-004-00, re failure to perform TS surveillance analyses of reactor coolant chemistry with fuel removed.  
 Commitments made by util listed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1 + 1  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-3 PD	1 1	STANG,J	1 1
INTERNAL: AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
<u>FILE CENTER</u>	1 1	NRR/DRCH/HOHB	1 1
NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
NRR/DSSA/SPLB	1 1	RES/DET/EIB	1 1
RGN3 FILE 01	1 1		
EXTERNAL: L ST LOBBY WARD	1 1	LMITCO MARSHALL	1 1
NOAC POORE,W.	1 1	NOAC QUEENER,DS	1 1
NRC PDR	1 1	NUDOCS FULL TXT	1 1

C  
A  
T  
E  
G  
O  
R  
Y  
1  
D  
O  
C  
U  
M  
E  
N  
T

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS  
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 18

Indiana Michigan  
Power Company  
Cook Nuclear Plant  
One Cook Plant  
Bridgman, MI 49106  
616 465 5901



March 18, 1999

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Operating License DPR-58  
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/99-004-00, "Failure to Perform Technical Specification Surveillance Analyses of Reactor Coolant Chemistry with Fuel Removed."

The following commitment has been identified:

- The root cause investigation for this event has not been completed. Based on the results of this investigation, additional corrective actions, including preventive actions may be developed. It is anticipated that, if significant changes are identified, supplemental information regarding corrective and preventive actions will be provided in an update to this LER.

Sincerely,

A handwritten signature in dark ink, appearing to read 'R. P. Powers'.

R. P. Powers  
Vice President

/mbd  
Attachment

c: J. E. Dyer, Region III  
P. A. Barrett  
D. F. Kunsemiller  
R. Whale  
D. Hahn  
Records Center, INPO  
NRC Resident Inspector

9903260063 990318  
PDR ADOCK 05000315  
S PDR