

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9904070423 DOC.DATE: 99/04/01 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH.NAME AUTHOR AFFILIATION
POWER,R.P." Indiana Michigan Power Co.
RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-007-00, "Calculations Show that Divider Barrier Between Upper & Lower Containment Vols May Be Overstressed." Commitments made be util are listed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 1
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
	PD3-3	PD	1	1	STANG,J		1	1
INTERNAL:	AEOD/SPD/RAB		2	2	AEOD/SPD/RRAB		1	1
	FILE CENTER		1	1	NRR/DRCH/HOHB		1	1
	NRR/DRCH/HQMB		1	1	NRR/DRPM/PECB		1	1
	NRR/DSSA/SPLB		1	1	RES/DET/EIB		1	1
	RGN3	FILE 01	1	1				
EXTERNAL:	L ST LOBBY WARD		1	1	LMITCO MARSHALL		1	1
	NOAC POORE,W.		1	1	NOAC QUEENER,DS		1	1
	NRC PDR		1	1	NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 18

Indiana Michigan
Power Company.
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



April 1, 1999

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/99-007-00, "Calculations Show that the Divider Barrier Between Upper and Lower Containment Volumes May Be Overstressed"

The following commitment has been identified in this submittal:

- Structural engineers are currently developing appropriate analyses of the loads and stresses on the steam generator enclosures. The results of these analyses will determine if an overstressed condition could have occurred and, if so, the safety significance of the overstressed condition.

Sincerely,

R. P. Powers
Vice President

/mbd
Attachment.

c: J. E. Dyer, Region III
P. A. Barrett
D. F. Kunsemiller
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector

9904070423 990401
PDR ADOCK 05000315
S PDR

