

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9904090203      DOC.DATE: 99/03/29    NOTARIZED: NO                  DOCKET #  
FACIL:50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M    05000316  
AUTH.NAME         AUTHOR AFFILIATION  
POWERS,R.P.        Indiana Michigan Power Co.  
RECIP.NAME         RECIPIENT AFFILIATION  
                     Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-001-00, degraded component cooling water flow to containment main stream line penetrations. Listed commitment identified in submittal.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 1  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

**NOTES:**

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-3 PD	1 1	STANG, J	1 1
INTERNAL: AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
<del>FILE CENTER</del>	1 1	NRR/DRCH/HOHB	1 1
NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
NRR/DSSA/SPLB	1 1	RES/DET/EIB	1 1
RGN3 FILE 01	1 1		
EXTERNAL: L ST LOBBY WARD	1 1	LMITCO MARSHALL	1 1
NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 18



Indiana Michigan  
Power Company  
Cook Nuclear Plant  
One Cook Plant  
Bridgman, MI 49106  
616 465 5601



March 29, 1999

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Operating License DPR-74  
Docket No. 50-316

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 316/99-001-00, "Degraded Component Cooling Water Flow to Containment Main Steam Line Penetrations."

The following commitment has been identified in this submittal:

Additional investigations to assess potential degradation to the concrete, liners and sleeves at these penetrations are ongoing. The results of those investigations, including identified root cause(s), preventive actions and safety significance will be provided when completed.

Sincerely,

A handwritten signature in dark ink, appearing to read "R. P. Powers".

R. P. Powers  
Vice President

/lr/b  
Attachment

c: J. E. Dyer, Region III  
P. A. Barrett  
D. F. Kunsemiller  
R. Whale  
D. Hahn  
Records Center, INPO  
NRC Resident Inspector

9904090203 990329  
PDR ADOCK 05000316  
S PDR