

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9904210026 DOC.DATE: 99/04/12 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH.NAME AUTHOR AFFILIATION
BAKKEN,A.C. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-009-00 re as-found RHR safety relief valve lift setpoint greater than TS limit. Commitments identified in submittal listed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 1
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	LPD3-1 PD	1 1	STANG, J	1 1
INTERNAL:	AEOD/SPD/RRAB	1 1	<u>FILE CENTER</u>	1 1
	NRR/DIPM/IOLB	1 1	NRR/DIPM/IQMB	1 1
	NRR/DRIP/REXB	1 1	NRR/DSSA/SPLB	1 1
	RES/DET/EIB	1 1	RGN3 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LMITCO MARSHALL	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIST OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL 16

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



April 12, 1999

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following interim report is being submitted:

LER 315/99-009-00, "As-Found Residual Heat Removal Safety Relief Valve Lift Setpoint Greater than Technical Specification Limit".

The following commitments were identified in this submittal:

- The root cause investigation for this condition has not been completed. As part of the investigation, instances where credit was taken for SV-103 being operable with a Power Operated Relief Valve inoperable will also be reviewed
- Upon completion of the investigation an update to this LER will be submitted, including any additional corrective and preventive actions.

Sincerely,

A handwritten signature in dark ink, appearing to read "A. Christopher Bakken, III".

A. Christopher Bakken, III
Site Vice President

/mbd
Attachment

c: J. E. Dyer, Region III
R. P. Powers
P. A. Barrett
D. F. Kunsemiller
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector

9904210026 990412
PDR ADOCK 05000315
S PDR

