

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9905170111 DOC. DATE: 99/05/10 NOTARIZED: NO DOCKET #  
FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316  
AUTH. NAME AUTHOR AFFILIATION  
RENCHECK, M.W. Indiana Michigan Power Co.  
RECIP. NAME RECIPIENT AFFILIATION  
Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-002-00 re TS 4.0.5 requirements not being met due to improperly performed test. Commitments identified in LER, listed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+3  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	LPD3-1 PD	1 1	STANG, J	1 1
INTERNAL:	AEOD/SPD/RRAB	1 1	<u>FILE CENTER</u>	1 1
	NRR/DIPM/IOLB	1 1	NRR/DIPM/IQMB	1 1
	NRR/DRIP/REXB	1 1	NRR/DSSA/SPLB	1 1
	RES/DET/EIB	1 1	RGN3 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LMITCO MARSHALL	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL 16

2  
8/11





May 10, 1998

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Operating License DPR-74  
Docket No. 50-316

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System (LER), the following report is being submitted:

LER 316/99-002-00, "Requirements of Technical Specification 4.0.5 Not Met Due to Improperly Performed Test".

The following commitments were identified in this submittal:

- Appendix J testing of the 2-CPN-41 penetration piping will be completed prior to restart of the unit.
- Procedures are being revised to strengthen the ISI program.
- A review of already prepared Job Orders will be conducted to determine if they contain notes which could lead to the misinterpretation of Code requirements.
- When the root cause investigation for this condition is completed, the results will be reviewed to determine if a supplement to this LER is needed.

Sincerely,

M. W. Rencheck  
Vice President - Nuclear Engineering

/mbd  
Attachment

JE22

9905170111 990510  
PDR ADOCK 05000316  
S PDR

c: J. E. Dyer, Region III  
R. P. Powers  
P. A. Barrett  
D. F. Kunsemiller  
R. Whale  
D. Hahn  
Records Center, INPO  
NRC Resident Inspector