

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9906070042 DOC.DATE: 99/06/01 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH.NAME AUTHOR AFFILIATION
BAKKEN,A.C. Indiana Michigan Power Co.
RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-S003-00, re nonconforming vital area barriers. Commitments made by util are listed.

DISTRIBUTION CODE: IE74T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 3
TITLE: Safeguards Phys Sec Event Pt. 73.71 (Public Available)

NOTES:

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
STANG, J		1	0				
INTERNAL:	AEOD/SPD/RRAB	1	1	FILE CENTER		1	1
	NMSS/FCSS/FCOB	1	1	NUDOCS FULLTEXT		1	1
	RGN3 01	1	1				
EXTERNAL:	NRC PDR	1	1				

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTR
DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 7 ENCL 6

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



June 1, 1999

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10CFR73, Appendix G, paragraph I(c) and 10CFR73.71(d), the following report is being submitted:

LER 315/99-S003-00, "Nonconforming Vital Area Barriers."

The following commitments were identified in this submittal:

- The openings for the cable tray wall penetrations between the Unit 1 and Unit 2 4 KV Rooms and the Unit 1 and 2 Reactor Cable Tunnels will be modified to ensure compliance with NUREG 0908. Compensatory measures will remain in place until the VA barriers are restored to conforming conditions.
- The ongoing Security Restart Readiness Self-Assessment team inspections will address the identification and correction of existing VA area barrier vulnerabilities due to design, materiel deficiencies or other causes prior to restart from the current outages of both units.
- Security will prepare and implement a procedure for future refueling outages to inspect VA barriers to identify and correct degraded and nonconforming conditions.

Sincerely,

A. Christopher Bakken, III
Site Vice President

/mbd
Attachment

c: J. E. Dyer, Region III
R. P. Powers
P. A. Barrett
D. F. Kunsemiller
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector

9906070042 990601
PDR ADOCK 05000315
S PDR

IE74