

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9908100138 DOC.DATE: 99/08/04 NOTARIZED: NO DOCKET #
FACIL:50-315.Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH.NAME AUTHOR AFFILIATION
BAKKEN,A.C. Indiana Michigan Power Co..
RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-029-01, "Fuel Handling Ventilation Sys Inoperable Due to Original Design Deficiency." Supplemental rept represents extensive rev to original LER & replaces rept entirely. Commitment made by licensee, listed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 7
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT			COPIES			RECIPIENT			COPIES		
ID CODE/NAME			LTTR ENCL			ID CODE/NAME			LTTR ENCL		
LPD3-1 PD			1	1		STANG, J			1	1	
INTERNAL:	FILE CENTER		1	1		NRR/DIPM/IOLB			1	1	
	NRR/DRIP/REXB		1	1		NRR/DSSA/SPLB			1	1	
	RES/DET/ERAB		1	1		RES/DRAA/OERAB			1	1	
	RGN3 FILE 01		1	1							
EXTERNAL:	L ST LOBBY WARD		1	1		LMITCO MARSHALL			1	1	
	NOAC POORE, W.		1	1		NOAC QUEENER, DS			1	1	
	NRC PDR		1	1		NUDOCS FULL TXT			1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 15 ENCL 15

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



August 4, 1999

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following supplemental report is being submitted:

LER 315/98-029-01, "Fuel Handling Area Ventilation System Inoperable Due to Original Design Deficiency". This supplemental report represents an extensive revision to the original LER and replaces that report in its entirety.

The following commitment was identified in this LER.

- The radiological analysis for the Spent Fuel Handling Accidents in the Auxiliary Building is being redone and is scheduled to be completed by August 30, 1999.

Sincerely,

A. Christopher Bakken III

Site Vice President

/lr/b
Attachment

c: J. E. Dyer, Region III
R. P. Powers
P. A. Barrett
G. P. Arent
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector

Test

9908100138 990804
PDR ADDCK 05000315
S PDR