

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC1 2000000000000000 3411111 4 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
01 REPORT SOURCE L 605000315 7120179 8122779 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 DURING THE INVESTIGATION OF A HIGH STEAM GENERATOR LEVEL INDICATION, FOR CHANNEL I  
03 LOOP 4, TRANSMITTER BLP 141 WAS FOUND TO BE 13 PERCENT OUT OF SPECIFICATION HIGH.  
04 THIS CONDITION WAS NON-CONSERVATIVE WITH RESPECT TO T.S. TABLE 2.2-1 ITEM 13 AND  
05 TABLE 3.3-1 ITEM 14.  
06  
07  
08

09 SYSTEM CODE I A 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE I 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER 7 9 21 22 23 24 26 27 28 29 30 31 32 REVISION NO. 0  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
C 18 X 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 N 25 B 0 8 0 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 THE TRANSMITTER (BLP-141) COULD NOT BE BROUGHT BACK INTO SPECIFICATION AND WAS  
11 REPLACED. THE DEFECTIVE TRANSMITTER WAS SENT TO BARTON FOR EVALUATION OF THE  
12 CAUSE OF THE FAILURE AND REPAIR. THIS INVESTIGATION WILL REMAIN OPEN AND  
13 A SUPPLEMENTAL LER WILL BE SUBMITTED WHEN AN ANSWER IS RECEIVED FROM BARTON.  
14 SEE ATTACHED SUPPLEMENT.  
7 8 9 80

15 FACILITY STATUS C 28 % POWER 0 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION ROUTINE OPERATOR READINGS 32  
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
7 8 9 10 11 12 13 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41  
7 8 9 10 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
7 8 9 10 80

20 PUBLICITY ISSUED DESCRIPTION 45  
7 8 9 10 80

NAME OF PREPARER S. D. DeLong

PHONE: 616-465-5901

8001020410

Dup NRC USE ONLY

GPO 917-96

SUPPLEMENT TO LER # 79-064/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THE ACTION REQUIREMENTS OF T.S. TABLE 2.2-1 ITEM 13 AND TABLE 3.3-1 ITEM 14  
WERE FULFILLED.