

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 0 5 0 0 0 3 1 6 7 0 1 1 5 8 0 8 0 2 0 8 8 0 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING INTEGRITY TESTING OF THE SOUTH SAFETY INJECTION TRAIN, EXCESSIVE
0 3 LEAKAGE FROM THE SAFETY INJECTION VALVE TO THE PRESSURIZER RELIEF
0 4 TANK WAS IDENTIFIED DURING REPAIRS TO SV-98, THE SOUTH SAFETY INJECTION
0 5 PUMP WAS INOPERABLE PER TECHNICAL SPECIFICATION 3.5.2. ACTION ITEMS
0 6 WERE FOLLOWED. THE NORTH SAFETY INJECTION TRAIN REMAINED OPERABLE DURING
0 7 THIS EVENT. NO PREVIOUS OCCURRENCES. PUBLIC HEALTH AND SAFETY WERE NOT
0 8 AFFECTED.
7 8 9 80

0 9 SYSTEM CODE S F 11 CAUSE CODE B 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE P 15 VALVE SUBCODE B 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 8 0 23 SEQUENTIAL REPORT NO. 0 0 2 27 OCCURRENCE CODE 0 3 28 REPORT TYPE L 30 REVISION NO. 0 32
21 22 24 26 29 31
ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER C 7 1 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE DISC INSERT, CROSBY PART NUMBER 084-519, WAS FOUND TO BE UNDERSIZED
1 1 AND DID NOT PROPERLY SEAL AGAINST THE SAFETY VALVE NOZZLE. THE SAFETY
1 2 VALVE'S DISC INSERT AND NOZZLE WERE REPLACED. SV-98 WAS REINSTALLED
1 3 FOLLOWING A BENCH TEST OF ITS PRESSURE SETPOINT. THE UNDERSIZED DISC
1 4 INSERT IS BELIEVED TO BE A MANUFACTURING ERROR.
7 8 9 80

1 5 FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION SPECIAL TEST 004 32
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 11 12 80

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 80

NAME OF PREPARER M. S. BROWN

PHONE: (616) 465-5901, EXT. 398

800 214 064

