

## LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT	58

**REPORT  
SOURCE**

0 1  
7 8

REPORT SOURCE L 6 0 5 0 0 0 3 1 5 7 0 1 2 3 8 0 8 0 2 2 2 8 0 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0 2 | WHILE PERFORMING AIRLOCK SEAL LEAK RATE TESTING PER STP.204, THE INNER  
0 3 | AIRLOCK LEAKAGE RATE EXCEEDED THE ACCEPTANCE CRITERIA OF THE TEST. THE  
0 4 | AIRLOCK WAS DECLARED INOPERABLE PER TECH. SPEC. 3.6.1.3.B. ACTION ITEMS  
0 5 | WERE FOLLOWED. NO PREVIOUS FAILURES HAVE BEEN EXPERIENCED WITH THIS  
0 6 | PORTION OF THE AIRLOCK SEAL. PUBLIC HEALTH AND SAFETY WERE NOT  
0 7 | AFFECTED BY THIS EVENT. THE OUTER AIRLOCK DOOR SEAL REMAINED OPERABLE  
0 8 | DURING THIS EVENT.

09		SYSTEM CODE S A		CAUSE CODE E	CAUSE SUBCODE B	COMPONENT CODE P E N E T R				COMP. SUBCODE A	VALVE SUBCODE Z
7	8	9	10	11	12	13	14	15	16		
LER/RO REPORT NUMBER 17		EVENT YEAR 8 0			SEQUENTIAL REPORT NO. 0 0 1			OCCURRENCE CODE 0 3		REPORT TYPE L	REVISION NO. 32
21	22	23	24	25	26	27	28	29	30	31	32
ACTION TAKEN E		FUTURE ACTION A	EFFECT ON PLANT Z	SHUTDOWN METHOD Z	HOURS 0 0 0		ATTACHMENT SUBMITTED N	NPRD-4 FORM SUB. N	PRIME COMP. SUPPLIER N	COMPONENT MANUFACTURER W 3 0 0	
33	34	35	36	37	38	39	40	41	42	43	44
18	19	20	21	22	23	24	25	26	27	28	29

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE SEAL FAILURE WAS TRACED TO A BROKEN ADJUSTMENT BOLT. ADJUSTING

1 1 OTHER ADJUSTING BOLTS RESULTED IN A SEAL WHICH MET THE ACCEPTANCE

1 2 CRITERIA OF STP.204. THE BROKEN BOLT WILL BE REPLACED DURING THE NEXT

1 3 UNIT REFUELING OUTAGE. CAUSE OF BROKEN BOLT COULD NOT BE DETERMINED.

1 4 THE SAME TEST PERFORMED 3 DAYS EARLIER WAS SUCCESSFUL.

7 8 9 FACILITY STATUS 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 OTHER STATUS 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 METHOD OF DISCOVERY 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 DISCOVERY DESCRIPTION 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 5 E 28 1 0 0 29 NA 30 B 31 SURVEILLANCE TESTING 32

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 34

7 8 9 10 11

AMOUNT OF ACTIVITY NA 35

44

LOCATION OF RELEASE 36

45 NA 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	(38)	NA	(39)	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

1		9		Z		42		NA		8002290436	
---	--	---	--	---	--	----	--	----	--	------------	--

7 8 9 10  
PUBLICATION (45)  
ISSUED (44) DESCRIPTION (45) NA  
2 0  
7 8 9 10 68 69 80  
NRC USE ONLY

NAME OF PREPARER M. S. BROWN

PHONE: 616-465-5901, EXT. 398

11