

**CONTROL BLOCK:**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	0	2	0	8	8	0	8	0	3	0	4	8	0	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0 2 | DURING NORMAL OPERATION, STEAM GENERATOR NUMBER 3 LEVEL INDICATION BECAME ERRATIC

0 3 | AND WAS DECLARED INOPERABLE, THUS, NOT MEETING THE INSTRUMENT OPERABILITY REQUIRE-

0 4 | MENTS OF T.S. TABLES: 3.3-1 ITEM 14 AND 3.3-3 ITEM 5.a AND 6.2. THE APPROPRIATE

0 5 | BISTABLES WERE PLACED IN THE TRIP POSITION AND NUMBER 3 STEAM GENERATOR LEVEL WAS

0 6 | PLACED IN MANUAL CONTROL. PREVIOUS OCCURRENCES INCLUDE: RO-050-315/79-52 AND 53.

0 7 |

0 8 |

7 8 9

SYSTEM CODE I A (11)		CAUSE CODE E (12)		CAUSE SUBCODE E (13)		COMPONENT CODE I N S T R U (14)				COMP. SUBCODE T (15)		VALVE SUBCODE Z (16)	
LER/RO REPORT NUMBER 8 0 (17)		EVENT YEAR 8 0 (21) 22		SEQUENTIAL REPORT NO. 0 0 9 (24) 26		OCCURRENCE CODE 0 3 (28) 29		REPORT TYPE L (30) 31		REVISION NO. 0 (32) 33			
ACTION TAKEN C (18) 33		FUTURE ACTION Z (19) 34		EFFECT ON PLANT Z (20) 35		SHUTDOWN METHOD Z (21) 36		HOURS 0 0 0 0 (22) 37-40		ATTACHMENT SUBMITTED N (23) 41		NPRD-4 FORM SUB. Y (24) 42	
PRIME COMP. SUPPLIER A (25) 43		COMPONENT MANUFACTURER B 0 8 0 (26) 44-47											

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

INVESTIGATION REVEALED THAT THE TRANSMITTER, MANUFACTURED BY BARTON-MODEL NO. 764, WAS CAUSING THE ERRATIC INDICATION. ANOTHER TRANSMITTER WAS INSTALLED, CALIBRATED AND THE AFFECTED STEAM GENERATOR LEVEL CHANNEL WAS RETURNED TO SERVICE. THE REPLACED TRANSMITTER WAS SENT TO ITT BARTON FOR REPAIR AND EVALUATION OF THIS PROBLEM.

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	E	(28)	1	0	0	(29)	NA				(30)	A	(31)	OPERATOR OBSERVATION				(32)
7	8	9		10	12			13				44	45	46				80	
ACTIVITY				CONTENT				AMOUNT OF ACTIVITY				LOCATION OF RELEASE							
RELEASED				OF RELEASE															
1	6	Z	(33)	1	Z	(34)		NA				(35)	NA				(36)		
7	8	9		10	11			44	45			80							
PERSONNEL EXPOSURES				DESCRIPTION															
NUMBER				TYPE															
1	7	0	(37)	1	0	0	(38)	NA				(39)							
7	8	9		11	12			13				80							
PERSONNEL INJURIES				DESCRIPTION															
NUMBER																			
1	8	0	(40)	NA				(41)											
7	8	9		11	12							80							
LOSS OF OR DAMAGE TO FACILITY				DESCRIPTION															
TYPE																			
1	9	Z	(42)	NA				(43)					8003110677						
7	8	9		10								80							
PUBLICITY				DESCRIPTION															
ISSUED																			
2	0	N	(44)	NA				(45)					NRC USE ONLY						
7	8	9		10								68	69				80		

NAME OF PREPARER J. L. Rischling

PHONE: 616-465-5901

Handwritten marks and scribbles in the top right corner.