

**LICENSEE EVENT REPORT**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	3	1	6	7	0	2	1	6	8	0	8	0	4	0	2	8	0	9
60	61							68	69					74	75								80
DOCKET NUMBER												EVENT DATE				REPORT DATE							

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

DURING A SURVEILLANCE TEST, THE PROXIMITY SWITCH FOR "D" MAIN TURBINE STOP

VALVE FELL OFF OF THE MOUNTING BRACKET. THIS PROXIMITY SWITCH PROVIDES

TURBINE STOP VALVE CLOSURE INDICATION FOR THE REACTOR PROTECTION SYSTEM.

THIS EVENT IS NON-CONSERVATIVE IN RESPECT TO T.S. TABLE 3.3-1 ITEM 18.b. THE

AFFECTED CHANNEL WAS PLACED IN THE TRIP CONDITION AS REQUIRED. PREVIOUS

OCCURRENCES INCLUDE: 050-316/80-04.

0	8																80					
7	8	9	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE						
			I	A	(11)	E	(12)	B	(13)	I	N	S	T	R	U	(14)	I	(15)	Z	(16)		
			9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26		
0	9	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.												
7	8	8	0	0	1	4	0	3	L	0												
		21	22	23	24	25	26	27	28	29	30	31	32									
(17) LER/RO REPORT NUMBER		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				
B	(18)	Z	(19)	Z	(20)	4	(21)	0	0	0	(22)	N	(23)	N	(24)	A	(25)	N	0	0	7	(26)
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

INVESTIGATION REVEALED THAT THE THREADS IN THE MOUNTING BRACKET WERE STRIPPED

OUT. THE HOLE WAS RETAPPED TO A LARGER SIZE AND NEW BOLTS WERE INSTALLED. THE

PROXIMITY SWITCH WAS THEN RETURNED TO SERVICE. THE MOUNTING BRACKETS FOR THE

OTHER PROXIMITY SWITCHES WERE ALSO CHECKED, NO ADDITIONAL PROBLEMS WERE DISCOVERED.

THIS EVENT WAS DETERMINED TO BE REPORTABLE ON MARCH 24, 1980

7	8	9	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	1	0	0	29	NA	B	31	SURVEILLANCE TEST 32	
7	8	9	ACTIVITY CONTENT RELEASED		AMOUNT OF ACTIVITY		LOCATION OF RELEASE					
1	6	4	33	2	34	NA	35	NA	36			
7	8	9	PERSONNEL EXPOSURES		TYPE		DESCRIPTION					
1	7	0	0	0	37	2	38	NA	39			
7	8	9	PERSONNEL INJURIES		DESCRIPTION							
1	8	0	0	0	40	NA		41				
7	8	9	LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION							
1	9	2	42	NA		43		8004080545				
7	8	9	PUBLICITY		DESCRIPTION							
2	0	N	44	NA		45		NRC USE ONLY				
7	8	9	ISSUED		DESCRIPTION							
2	0	N	44	NA		45		68		69		

NAME OF PREPARER

J. L. RISCHLING

PHONE:

616-465-5901

