

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 0 5 0 0 0 3 1 6 7 0 3 3 1 8 0 8 0 4 2 5 8 0 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING NORMAL OPERATION, RADIATION MONITOR R-11 ALARMED AND WOULD NOT
0 3 RESET. INVESTIGATION REVEALED THAT THE SAMPLE PUMP FOR R-11 AND R-12
0 4 WAS NOT PROVIDING SUFFICIENT FLOW. THE SAMPLE PUMP WAS REMOVED FROM
0 5 SERVICE CONSTITUTING AN INOPERABLE RAD. MONITOR SYSTEM PER T.S. 3.3.3.1
0 6 AND TABLE 3.3-6. THE ACTION REQUIREMENTS WERE MET. THIS EVENT HAD NO
0 7 EFFECT ON PUBLIC HEALTH AND SAFETY. SIMILAR EVENTS INCLUDE RO 79-034/
0 8 03L-0, 80-013/03L-0 AND FOR DOCKET NO. 050-315: (CONTINUED)
7 8 9 80

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
B B 11 E 12 B 13 P U M P X X 14 H 15 Z 16
7 8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 0 0 1 8 0 3 L 0
21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
C 18 F 19 Z 20 Z 21 0 0 0 Y 23 N 24 A 25 W 1 2 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 FAILURE WAS DUE TO WEAR OF THE PUMP. THE COMPLETE PUMP AND THE RUBBER
1 1 SPIDER IN THE LOVEJOY L-100 PUMP TO MOTOR COUPLING WERE REPLACED AND THE
1 2 AIR SAMPLER TESTED. PLANS ARE TO REPLACE THE ENTIRE SYSTEM AS PART OF
1 3 MODIFICATION RFC DC 12-2448.
1 4
7 8 9 80

1 5 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
E 28 1 0 0 0 29 N/A A 31 OPERATOR OBSERVATION
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
Z 33 Z 34 N/A N/A
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
0 0 0 37 Z 38 N/A
7 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
0 0 0 40 N/A
7 8 9 10 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
Z 42 N/A
7 8 9 10 80

2 0 PUBLICITY ISSUED DESCRIPTION (45)
N 44 N/A
7 8 9 10 80

NAME OF PREPARER DAVID G. WIZNER

PHONE: 616-465-5901, EXT. 1398

NRC USE ONLY

()

SUPPLEMENT TO LER#80-018/03L-0

SUPPLEMENT TO EVENT DESCRIPTION AND PROBABLE CONSEQUENCES:

RO 79-012/03L-0 AND 79-048/03L-0.

