

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1																																								
7	8																																								
REPORT SOURCE		L	6	0	5	0	0	0	3	1	5	7	0	3	2	6	8	0	8	0	4	2	5	8	0	9															
		60	61	DOCKET NUMBER										68	69	EVENT DATE										74	75	REPORT DATE										80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	9		S	F	11	D	12	Z	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16					
7		8	9		10		11		12							18		19		20					
17		LER/RO REPORT NUMBER		EVENT YEAR				SEQUENTIAL REPORT NO.						OCCURRENCE CODE		REPORT TYPE				REVISION NO.					
			8	0				0	0	7				0	3		L			0					
			21		22		23				24			26		27			30		31		32		
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
G	18	Z	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	Z	25	Z	9	9	9	26			
			33		34		35							40		41			42				44		47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS (28) 1 5 E 7 8 9
 % POWER 1 0 0 (29) 10 12 13
 OTHER STATUS (30) NA 44
 METHOD OF DISCOVERY (31) B 45 46
 DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION 80
 ACTIVITY CONTENT RELEASED OF RELEASE (33) 1 6 Z 7 8 9
 AMOUNT OF ACTIVITY (35) NA 10 11 44
 LOCATION OF RELEASE (36) NA 45 80

7	8	9	11	12	13
PERSONNEL INJURIES					
NUMBER	DESCRIPTION (41)				
	NA				

TYPE		DESCRIPTION
1	9	NA


7 8 9 10

8005020272

PUBLICITY (45) NRC USE ONLY

ISSUED (44) 2 0 N NA

PHONE: (616) 465-5901 EXT. 1316



SUPPLEMENT TO LER# 80-007/03L-0

SUPPLEMENT TO EVENT DESCRIPTION AND PROBABLE CONSEQUENCES:

WERE REVISED TO CONFORM TO THE 31 DAY TESTING REQUIREMENT. NO FURTHER ACTION IS PLANNED.



1-1-74