

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8811100046 DOC. DATE: 88/10/20 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME: SMITH, W.G. AUTHOR AFFILIATION: Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP. NAME: RECIPIENT AFFILIATION: Document Control Branch (Document Control Desk)

SUBJECT: Special rept: Fire Door 371, separating new containment access
 bldg & auxiliary bldg crane bay inoperable more than 7 days.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD3-1 LA		1	1		PD3-1 PD		1	1
	SCOTT, W		1	1					
INTERNAL:	ACRS MICHELSON		1	1		ACRS MOELLER		2	2
	ACRS WYLIE		1	1		AEOD/DOA		1	1
	AEOD/DSP/TPAB		1	1		ARM/DCTS/DAB		1	1
	DEDRO		1	1		NRR/DEST/ADS 7E		1	1
	NRR/DEST/CEB 8H		1	1		NRR/DEST/ESB 8D		1	1
	NRR/DEST/ICSB 7		1	1		NRR/DEST/MEB 9H		1	1
	NRR/DEST/MTB 9H		1	1		NRR/DEST/PSB 8D		1	1
	NRR/DEST/RSB 8E		1	1		NRR/DEST/SGB 8D		1	1
	NRR/DLPQ/HFB 10		1	1		NRR/DLPQ/QAB 10		1	1
	NRR/DOEA/EAB 11		1	1		NRR/DREP/RAB 10		1	1
	NRR/DREP/RPB 10		2	2		NRR/DREP/SIB 9A		1	1
	NUDOCS-ABSTRACT		1	1		REG FILE 02		1	1
	RES/DSIR/EIB		1	1		RES/DSR/PRAB		1	1
	RGN3 FILE 01		1	1					
EXTERNAL:	EG&G WILLIAMS, S		4	4		FORD BLDG HOY, A		1	1
	H ST LOBBY WARD		1	1		LPDR		1	1
	NRC PDR		1	1		NSIC HARRIS, J		1	1
	NSIC MAYS, G		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 42 ENCL 41

Incident 2
gh

Indiana Michigan
Power Company
Cook Nuclear Plant
P.O. Box 458
Bridgman, MI 49106
616 465 5901



October 20, 1988

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315, 50-316
License Nos. DPR-58, DPR-74

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

ATTN: A.B. Davis


Dear Mr. Davis:

This special report is being submitted in accordance with Technical Specification 3.7.10 Action A, to inform you that Fire Door 371, separating the new Containment Access Building and the Auxiliary Building Crane Bay, has been inoperable for longer than seven days.

Fire Door 371 was installed as part of the new Containment Access Building constructed for the Unit 2 Steam Generator Repair Project. Due to numerous repairs and repetitive hardware failures, we have concluded that this door is not designed to withstand the high traffic service to which it is being subjected. Permanent correction of this situation is being pursued. We will provide you with the schedule for correction when that has been determined.

Upon declaring Fire Door 371 inoperable, fire watches, as required by Technical Specification 3.7.10 Action A, were initiated and will remain in effect until all repairs are completed.

Respectfully,


W.G. Smith, Jr.
Plant Manager

/bab

c: See Attached Distribution

8811100046 881020
PDR ADOCK 05000315
S PDC

IE22
1/0

cc: D.H. Williams, Jr.
A.B. Davis, Region III
M.P. Alexich
R.F. Kroeger
J.E. Borggren
R.W. Jurgensen
NRC Resident Inspector
J.F. Stang
R.C. Callen
G.Charnoff, Esq.
Dottie Sherman, ANI Library
D.Hahn
INPO
PNSRC
A.A. Blind
P.A. Barrett/B. Lauzau