

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8901300170 DOC. DATE: 89/01/18 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH. NAME AUTHOR AFFILIATION
 SMITH, W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890119, Fire Door 392 inoperable due to
 screws missing from astragal covering gap between 2 doors.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1	PD3-1 PD	1
	STANG, J	1		
INTERNAL:	ACRS MICHELSON	1	ACRS MOELLER	2
	ACRS WYLIE	1	AEOD/DOA	1
	AEOD/DSP/TPAB	1	AEOD/ROAB/DSP	2
	ARM/DCTS/DAB	1	DEDRO	1
	NRR/DEST/ADE 8H	1	NRR/DEST/ADS 7E	1
	NRR/DEST/CEB 8H	1	NRR/DEST/ESB 8D	1
	NRR/DEST/ICSB 7	1	NRR/DEST/MEB 9H	1
	NRR/DEST/MTB 9H	1	NRR/DEST/PSB 8D	1
	NRR/DEST/RSB 8E	1	NRR/DEST/SGB 8D	1
	NRR/DLPQ/HFB 10	1	NRR/DLPQ/QAB 10	1
	NRR/DOEA/EAB 11	1	NRR/DREP/RAB 10	1
	NRR/DREP/RPB 10	2	NRR/DRIS/SIB 9A	1
	NUDOCS-ABSTRACT	1	REG FILE 02	1
	RES/DSIR/EIB	1	RES/DSR/PRAB	1
	RGN3 FILE 01	1		
EXTERNAL:	EG&G WILLIAMS, S	4	FORD BLDG HOY, A	1
	H ST LOBBY WARD	1	LPDR	1
	NRC PDR	1	NSIC HARRIS, J	1
	NSIC MAYS, G	1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 45 ENCL 44

R
I
D
S
/
A
D
S
/
A
D
D
S

FA
[Signature]

Indiana Michigan
Power Company
Cook Nuclear Plant
P.O. Box 458
Bridgman, MI 49106
616 465 5901



January 18, 1989

Donald C. Cook Nuclear Plant Units 1 & 2
Docket Nos. 50-315, 50-316
License Nos. DPR-58, DPR-74

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Dear Mr. Davis:

This letter is to inform you that Fire Doors 392 and 386 have been inoperable longer than the seven days allowed by Technical Specification 3.7.10 Action a.

Fire Door 392, separating fire zones 43 and 91, was declared inoperable on December 19, 1988 due to screws being missing from the astragal covering the gap between the two sections of the door. Due to the length of time required to obtain certified parts, the door was not repaired and declared operable until January 18, 1989. At the time the door was declared inoperable, a roving fire watch patrol was established as required by Technical Specification 3.7.10 Action a, and was maintained until the door was returned to operable status.

Fire Door 386, separating fire zones 39 and 34B, was declared inoperable on December 16, 1988 due to a broken closing device. Due to the requirement to use only certified parts for fire door repairs, we are having to wait until the required parts certification is obtained before completing repairs. It is expected that this fire door will be repaired and returned to operable status by February 15, 1989. At the time Fire Door 386 was declared inoperable a roving fire watch patrol was established as required by Technical Specification 3.7.10 Action a. This fire watch patrol will remain in effect until the fire door can be returned to operable status.

Respectfully,


W.G. Smith, Jr.
Plant Manager

8901300170 890118
PDR ADDCK 05000315
S PNU

WGS:afh

LE22
1/0

c: D. H. Williams, Jr.
C. J. Paperiello, Region III
M. P. Alexich
P. A. Barrett
J. E. Borggren
R. F. Kroeger
NRC Resident Inspector
Wayne Scott, NRC
R. C. Callen
G. Charnoff, Esq.
Dottie Sherman, ANI Library
D. Hahn
INPO
PNSRC
A. A. Blind
S. J. Brewer/B. P. Lauzau