

## ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8905110133 DOC.DATE: 89/05/01 NOTARIZED: NO DOCKET #  
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH.NAME AUTHOR AFFILIATION  
 SMITH,W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP.NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept:on 890324,free field seismic trigger removed &  
 remained inoperable for longer than 30 days.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

## NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-1 LA	1 1	PD3-1 PD	1 1
STANG,J	1 1		
INTERNAL: ACRS MICHELSON	1 1	ACRS MOELLER	2 2
ACRS WYLIE	1 1	AEOD/DOA	1 1
AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
DEDRO	1 1	IRM/DCTS/DAB	1 1
NRR/DEST/ADE 8H	1 1	NRR/DEST/ADS 7E	1 0
NRR/DEST/CEB 8H	1 1	NRR/DEST/ESB 8D	1 1
NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/QAB 10	1 1
NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
NRR/DRTS/SIB 9A	1 1	NUDOCS-ABSTRACT	1 1
REG FILE 02	1 1	RES/DSIR/EIB	1 1
RES/DSR/PRAB	1 1	RGN3 FILE 01	1 1
EXTERNAL: EG&G WILLIAMS,S	4 4	FORD BLDG HOY,A	1 1
L ST LOBBY WARD	1 1	LPDR	1 1
NRC PDR	1 1	NSIC MAYS,G	1 1
NSIC MURPHY,G.A	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 44 ENCL 43

Indiana Michigan  
Power Company  
Cook Nuclear Plant  
P.O. Box 458  
Bridgman, MI 49106  
616 465 5901



May 1, 1989

Donald C. Cook Nuclear Plant Units 1 and 2  
Docket Nos. 50-315; 50-316  
License Nos. DPR-58; DPR-74

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Attn: A. B. Davis

Dear Mr. Davis:


This special report is submitted, in accordance with Technical Specification 3.3.3.3 Action b, to inform you that the Free Field Seismic Trigger has been inoperable for longer than 30 days.

The trigger was removed from the Free Field Monitor on March 24, 1989, and used to replace the Reactor Pit Seismic Trigger which had been damaged during calibration. The model of the trigger that was damaged is no longer available and a design change was approved to allow the purchase and installation of a comparable substitute. However, since it was uncertain how long it would be before a new trigger could be obtained and since the reactor pit may not have been accessible at that time, it was decided to replace the Reactor Pit Seismic Trigger with one taken from the Free Field, which is accessible at all times.

It should be noted that the triggers are normally wired in parallel and, therefore, perform the same function.

It is anticipated that the new trigger will arrive and be installed by July 31, 1989.

Respectfully,

  
W. G. Smith, Jr.  
Plant Manager

/mmp

8905110133 890501  
PDR ADOCK 05000315  
S PDC

IE22  
11

cc: D. H. Williams, Jr.  
C. J. Paperiello, Region III  
M. P. Alexich  
P. A. Barrett  
J. E. Borggren  
R. F. Kroeger  
NRC Resident Inspector  
W. Scott, NRC  
R. C. Callen  
G. Charnoff, Esq.  
Dottie Sherman, ANI Library  
D. Hahn  
INPO  
PNSRC  
A. A. Blind  
S. J. Brewer / B. P. Lauzau