

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9011070281 DOC.DATE: 90/10/30 NOTARIZED: NO DOCKET #  
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
 AUTH.NAME AUTHOR AFFILIATION  
 BAKER,D.L. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP.NAME RECIPIENT AFFILIATION  
 MORLEY,F. Michigan, State of

SUBJECT: NPDES noncompliance notification: on 901025, five unmonitored discharges from turbine room sump occurred.

DISTRIBUTION CODE: IE23D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Environmental Event Report (per Tech Specs)

### NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD3-1 LA		3	1		PD3-1 PD		1	1
	COLBURN,T.		1	1					
INTERNAL:	AEOD/DSP/TPAB		1	1		AEOD/PTB		1	1
	NRR/DREP/PEPB9D		1	1		NRR/PMAS/ILRB12		1	1
	OGC/HDS1		1	1		<del>REG-ETHE-01</del>		1	1
	RGN3		1	1		RGN2/DRSS/EPRPB		1	1
EXTERNAL:	NRC PDR		1	1		NSIC		1	1

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 15 ENCL 15

Indiana Michigan  
Power Company  
One Summit Square  
P.O. Box 60  
Fort Wayne, IN 46801  
219 425 2111



Fred Morley, District Supervisor  
Surface Water Quality Division  
Michigan Department of Natural Resources  
621 North 10th Street  
P. O. Box 355  
Plainwell, MI 49080

October 30, 1990

Dear Mr. Morley:

RE: NPDES Permit No. MI0005827  
Cook Nuclear Plant  
Bridgman, Michigan

Between the hours of 0000 and 0345 on 10/25/90, five (5) unmonitored discharges from the Turbine Room Sump (TRS) occurred. These resulted from a loss of flow to the TRS sample line caused by blockage downstream. The TRS was isolated immediately upon discovery and a job order was written to make repairs. In the interim, the Chemistry Department is performing pH sampling prior to discharging the sump. It is estimated that 250,000 gallons of water were released prior to the Turbine Room Sump being isolated.

We have no reason to believe that any effluent limitations were exceeded during this period.

Very truly yours,

A handwritten signature in cursive script that reads 'Donald L. Baker'.

Donald L. Baker  
Environmental Affairs Director

c: A. B. Davis - NRC Region III  
Bruce Jorgenson - NRC Resident Inspector  
Dr. T. E. Murley - NRC Document Control ✓

000029

50-315  
50-316

9011070281 901030  
PDR ADDCK 05000315  
S PNU

1623  
1/0

