

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION # BR:9209300017 DOC.DATE: 92/09/21 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 AUTH.NAME AUTHOR AFFILIATION
 FITZPATRICK,E. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP.NAME RECIPIENT AFFILIATION
 MURLEY,T.E. Document Control Branch (Document Control Desk)

SUBJECT: Provides closeout info for NRC Bulletin 89-001, Suppl 2,
 "Failure of Westinghouse SG Tube Mechanical Plugs." All
 affected plugs, required to be removed prior to OL expiration
 removed during Cycle 12-13 refueling outage & replaced.

DISTRIBUTION CODE: IE31D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Bulletin Response 89-01 re Failure of Westinghouse Steam Gen. Mech. T

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-1 LA	1 1	PD3-1 PD	1 1
STANG,J	1 1		
INTERNAL: AEOD/DOA	1 1	NRR/DET/EMCB 9H	1 1
NRR/DET/EMEB 7E	1 1	NRR/DOEA/OEAB11	1 1
NRR/DOEA/OGCB11	1 1	NRR/DREP/PEPB9D	1 1
NRR/DST-8E2	1 1	NRR/PMAS/ILRB12	1 1
REG FILE 02	1 1	RES/DSIR/EIB	1 1
RGN3 FILE 01	1 1		
INTERNAL: NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL 16 0

NO-1
 dhp



AEP:NRC:1096E

Donald C. Cook Nuclear Plant Unit 1
License No. DPR-58
Docket No. 50-315
CLOSE OUT ACTION FOR NRC BULLETIN 89-01 SUPPLEMENT 2:
FAILURE OF WESTINGHOUSE STEAM GENERATOR TUBE MECHANICAL PLUGS

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Attn: T. E. Murley

September 21, 1992

Dear Dr. Murley:

The purpose of this letter is to provide close-out information for NRC Bulletin 89-01 Supplement 2 "Failure of Westinghouse Steam Generator Tube Mechanical Plugs."

Our letter dated July 29, 1991 (AEP:NRC:1096C) provided our response to NRC Bulletin 89-01 Supplement 2. In that letter, we committed to replacing all affected Inconel 600 mechanical plugs in Unit 1 prior to the plugs exceeding the effective full power day (EFPD) limits established by Westinghouse. By this letter, we are informing you that all affected plugs that were required to be removed prior to expiration of the operating license were removed during the Unit 1 Cycle 12-13 refueling outage. The affected plugs were either replaced with Inconel 690 plugs or the tubes were recovered by sleeving.

Sincerely,

E. E. Fitzpatrick
Vice President

swm

2500..

9209300017 920921
PDR ADDCK 05000315
Q PDR

IE31

Dr. T. E. Murley

-2-

AEP:NRC:1096E

cc: D. H. Williams, Jr.
A. A. Blind - Bridgman
J. R. Padgett
G. Charnoff
NFEM Section Chief
A. B. Davis - Region III
NRC Resident Inspector - Bridgman