

# ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9303090182, DOC.DATE: 93/03/01 NOTARIZED: YES DOCKET #  
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316  
 AUTH.NAME AUTHOR AFFILIATION  
 FITZPATRICK,E. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP.NAME RECIPIENT AFFILIATION  
 MURLEY,T.E. Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC Bulletin 90-001, Supplement 1, "Loss of  
 Fill-Oil in Transmitters Manufactured by Rosemount." No subj  
 transmitters installed at Cook Nuclear Plant.

DISTRIBUTION CODE: IE39D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3  
 TITLE: Part 40, NMSS/IMSB Corresp: Incoming Appls, Amdts, Addl Info.

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 PD	1 1	DEAN,W	1 1
INTERNAL:	NRR LE,N	1 1	NRR/DORS/OGCB	1 1
	NRR/HICB	1 1	NRR/OEAB	2 2
	<u>REG FILE</u> 02	1 1	RES/EMEB	1 1
	RGN3 FILE 01	1 1		
EXTERNAL:	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 12 ENCL 12



AEP:NRC:1109A

Donald C. Cook Nuclear Plant Units 1 and 2  
Docket Nos. 50-315 and 50-316  
License Nos. DPR-58 and DPR-74  
BULLETIN 90-01, SUPPLEMENT 1: LOSS OF FILL-OIL  
IN TRANSMITTERS MANUFACTURED BY ROSEMOUNT

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Attn: T. E. Murley

March 1, 1993

Dear Dr. Murley:

The following information is provided in response to NRC Bulletin 90-01, Supplement 1. Bulletin 90-01, Supplement 1 requires the licensees to take additional actions to resolve the loss of fill-oil problem in Rosemount Model 1153 Series B, Model 1153 Series D, and Model 1154 transmitters.

There are no Rosemount Model 1153 Series B, Model 1153 Series D or Model 1154 transmitters installed at Cook Nuclear Plant.

Based on this statement, we will take no further actions with respect to Supplement 1 of Bulletin 90-01.

This letter is submitted pursuant to 10 CFR 50.54(f) and, as such, an oath statement is attached.

Sincerely,

A handwritten signature in dark ink, appearing to read 'E. E. Fitzpatrick'.

E. E. Fitzpatrick  
Vice President

eh

Attachment

050025

JE39

Dr. T. E. Murley

-2-

AEP:NRC:1109A

cc: A. A. Blind - Bridgman  
J. P. Padgett  
G. Charnoff  
A. B. Davis - Region III  
NRC Resident Inspector - Bridgman  
NFEM Section Chief

STATE OF OHIO)  
COUNTY OF FRANKLIN)

E. E. Fitzpatrick, being duly sworn, deposes and says that he is the Vice President of licensee Indiana Michigan Power Company, that he has read the forgoing Response to Bulletin 90-01, Supplement 1: Loss of Fill-oil In Transmitters Manufactured by Rosemount and knows the contents thereof; and that said contents are true to the best of his knowledge and belief.

E. E. Fitzpatrick

Subscribed and sworn to before me this 2nd

day of March, 1993.

Rita D. Hill  
NOTARY PUBLIC

RITA D. HILL  
NOTARY PUBLIC, STATE OF OHIO  
MY COMMISSION EXPIRES 6-28-94