

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

WHILE INVESTIGATING SIMILAR EVENT IN THE OTHER UNIT.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

A TYPE C LEAK TEST WAS PERFORMED ON BOTH (SEE ATTACHED SUPPLEMENT).

PHONE: _____

ATTACHMENT TO LER #80-012/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

R-156 AND R-157, BOTH VALVES SUCCESSFULLY PASSED. AT THIS TIME THESE CHECK VALVES WERE ADDED TO THE APPLICABLE SURVEILLANCE TEST PROCEDURE INCLUDING THEM IN THE TYPE C LEAKAGE TEST. A SEPARATE REPORT IS BEING SUBMITTED FOR THESE VALVES IN UNIT 2.

