

CONTROL BLOCK:

						1
--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	0	7	2	1	8	0	8	0	8	1	9	8	0	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

02 | DURING NORMAL OPERATION, WHILE INVESTIGATING FREQUENT FILTER NOT IN MOTION ALARMS

03 | ON THE CONTAINMENT APD (R-11), THE FILTER PAPER MOTOR BOUND-UP STOPPING THE

04 | FILTER PAPER, RENDERING R-11 INOPERABLE. THIS IS NON-CONSERVATIVE IN RESPECT

05 TO T.S. 3.4.6.1 AND TABLE 3.3-6 ITEM 2.A. THE APPROPRIATE ACTION REQUIREMENTS

06 WERE FULFILLED. PREVIOUS OCCURRENCES INCLUDE: 050-315/80-11, 79-8, 12,48 AND

07 | 050-316/80-13,18,22,23,79-34.

A horizontal number line is shown, labeled with 7, 8, and 9. A point is marked on the line between 8 and 9, specifically at the 25th percentile (0.25) of the interval. This point is labeled with a box containing '0' and '8' above it, and '25' below it.

SYSTEM CODE B B (11)		CAUSE CODE E (12)		CAUSE SUBCODE B (13)		COMPONENT CODE M O T O R S (14)				COMP. SUBCODE Z (15)		VALVE SUBCODE Z (16)	
7 8		9 10		11 12		13 14 15 16 17 18				19 20		21 22	
(17) LER/RO REPORT NUMBER		EVENT YEAR 8 0 (21) (22)		SEQUENTIAL REPORT NO. 0 2 9 (24) (25) (26)		OCCURRENCE CODE 0 3 (28) (29)		REPORT TYPE L (30)		REVISION NO. 0 (32)			
ACTION TAKEN C (18)		FUTURE ACTION F (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22) (23) (24) (25)		ATTACHMENT SUBMITTED N (23)		NPRD-4 FORM SUB. Y (24)	
33 34		35 36		37 38 39 40		41 42		43 44		45 46 47 48			
PRIME COMP. SUPPLIER N (25)		COMPONENT MANUFACTURER B 0 6 7 (26)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | INVESTIGATION REVEALED THE FILTER PAPER DRIVE MOTOR (MANUFACTURED BY BARBER

COLEMAN COMPANY TYPE PZDJ 10-525) HAD A BAD BEARING. THE MOTOR WAS REPLACED

112 AND THE CONTAINMENT APD WAS RETURNED TO SERVICE AFTER BEING OUT OF SERVICE FOR

1 3 6 HOURS AND 43 MINUTES. FUTURE PLANS INCLUDE REPLACING THE PRESENT CONTAINMENT

14 | APD'S.

FACILITY STATUS (28) 1 5 E
 % POWER 1 0 0 (29) NA OTHER STATUS (30)
 METHOD OF DISCOVERY A (31) OPERATIONAL EVENT DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 7 33 Z 34 NA NA

7 8 9 10 11 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	(37) Z (38) NA					

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	NA

		8	9	10	11	12	
		LOSS OF OR DAMAGE TO FACILITY (43)					
		TYPE		DESCRIPTION			
1	9	Z	(42)	NA			

2		0		ISSUED		N		44		PUBLICITY DESCRIPTION		45		NA		68		69		NRC USE ONLY		80	
---	--	---	--	--------	--	---	--	----	--	-----------------------	--	----	--	----	--	----	--	----	--	--------------	--	----	--

NAME OF PREPARER J. L. RISCHLING

PHONE: 6L6-465-5901

