

CONTROL BLOCK:

--	--	--	--	--	--

!

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	3

REPORT SOURCE

L	(6)	0	5	0	0	0	3	1	5	(7)	0	8	1	7	8	0	(3)	0	9	1	2	8	0	(9)
60	61	DOCKET NUMBER					63	69	EVENT DATE					74	REPORT DATE					80				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | DURING AN ICE CONDENSER INSPECTION, TWO INTERMEDIATE DECK DOORS WERE

013 | FOUND FROZEN AND DECLARED INOPERABLE PER T.S. 3.6.5.3. ACTION REQUIRE-

014 | MENTS WERE MET. THE OTHER 190 DOORS REMAINED OPERABLE. THIS EVENT

015 | HAD NO PUBLIC HEALTH AND SAFETY CONSEQUENCES. 'PREVIOUS EVENTS INCLUDE:

016 | RO 79-036/03L-0; 79-045/036-0; 79-060/03L-0 AND 80-010/03L-0.

017 |

018 |

SYSTEM CODE S B 11		CAUSE CODE B 12		CAUSE SUBCODE A 13		COMPONENT CODE H T E X C H 14		COMP. SUBCODE D 15		VALVE SUBCODE Z 16	
9 10		11		12		13 18		19		20	
LEP NO. REPORT NUMBER 17		EVENT YEAR 8 0 21 22		SEQUENTIAL REPORT NO. 0 2 1 24 25 26		OCCURRENCE CODE / 0 3 27 28 29		REPORT TYPE L 30 31		REVISION NO. 0 32	
ACTION TAKEN X 18		FUTURE ACTION F 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 38 39 40		ATTACHMENT SUBMITTED N 23 41	
33 34		35		36		42		43		44 45 46	
NPRD-1 FORMULS. N 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER W 1 2 0 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

THE ICE ON THE FROZEN DOORS WAS CHIPPED FREE AND REMOVED. THE DOORS WERE
VERIFIED OPERABLE. TOP DECK DOOR DIVIDER BEAMS WERE FOUND TO BE THE
SOURCE OF THE WATER. DESIGN CHANGE RFC DC 12-1791 HAS BEEN SUBMITTED
TO INSULATE THOSE BEAMS TO PREVENT CONDENSATION.

FACILITY STATUS			4 POWER			OTHER STATUS (39)			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION (32)			
1	5	C	(33)	0	4	8	(39)	POWER ASCENSION	9	(31)	OPERATOR OBSERVATION				
ACTIVITY CONTENT			10 RELEASED OF RELEASE			12 AMOUNT OF ACTIVITY (25)			45 NA			LOCATION OF RELEASE (36)			
1	5	Z	(33)	Z	(34)	NA									
PERSONNEL EXPOSURES			11 NUMBER			12 TYPE			DESCRIPTION (39)						
1	7	0	0	0	(3)	Z	(35)	NA							
PERSONNEL INJURIES			11 NUMBER			12 DESCRIPTION (41)									
1	5	0	0	0	(40)	NA									
LOSS OF OR DAMAGE TO FACILITY			11 TYPE			12 DESCRIPTION (43)									
1	5	Z	(42)	NA											
PUBLICITY			10 ISSUED			DESCRIPTION (45)						NRC USE ONLY			
2	0	N	(44)	NA											

NAME OF PREPARED DAVID G. WILNER

PHONE: 615-465-5901, EXT. 1057

8009190509.

