

## LICENSEE EVENT REPORT

**CONTROL BLOCK:**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	3	1	5	7	0	9	1	6	8	0	8	1	0	0	3	8	0	9															

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0 2 | DURING NORMAL OPERATION THE STEAM GENERATOR 2 CHANNEL 3 LEVEL INDICATION WAS FOUND TO  
0 3 | BE INDICATING 6 PERCENT LOWER THAN THE ASSOCIATED CHANNELS FOR THAT GENERATOR.  
0 4 | INITIAL INVESTIGATION REVEALED THAT THE LEVEL TRANSMITTER (BLP 122) OUTPUT WAS SLOWLY  
0 5 | DRIFTING DOWN. THIS CONDITION WAS NON-CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFI-  
0 6 | CATION TABLE 3.3-4 ITEM 5a. PREVIOUS OCCURANCES INCLUDE RO-050-315/79-52, 64,80/13 AND  
0 7 | RO-050-316/80-009.

08		9		80	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE	
I	B	11	E	12	X
COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE	
I	N	S	T	R	U
14	T	15	Z	16	
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	
8	0	22	0	2	3
LER/RO REPORT NUMBER		SHUTDOWN METHOD		ATTACHMENT SUBMITTED	
17	18	Z	19	A	20
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT	
B	33	34	A	35	A
NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
Y	24	N	25	B	0
HOURS		REVISION NO.		COMPONENT MANUFACTURER	
0	0	2	9	0	26

**CAUSE DESCRIPTION AND CORRECTIVE ACTIONS\* (27)**

1 0 THE CAUSE OF THE TRANSMITTER DRIFT WAS DUE TO A PINHOLE LEAK IN THE IMPULSE LINE AT

1 1 THE SOCKET WELD DOWNSTREAM OF THE ROOT VALVE FOR BLP-122. THE UNIT WAS SHUT DOWN,

1 2 REPAIRS MADE AND THE GENERATOR LEVEL PROTECTION LOOP PLACED BACK INTO SERVICE.

1 3 THE ACTION REQUIREMENTS OF TECHNICAL SPECIFICATION TABLE 3.3-3 ITEM 5a WERE FULFILLED.

1 4 NO FURTHER ACTION IS PLANNED.

7	8	9	FACILITY STATUS											METHOD OF DISCOVERY											DISCOVERY DESCRIPTION											80		
1	5	E	28	098				29	NA				30	A	31	OPERATOR OBSERVATION										32												80
7	8	9	ACTIVITY CONTENT											LOCATION OF RELEASE											80													
1	6	Z	33	Z	34	NA				35	NA											36												80				
7	8	9	PERSONNEL EXPOSURES											LOCATION OF RELEASE											80													
1	7	0	0	0	37	Z	38	NA				39												80														
7	8	9	PERSONNEL INJURIES											LOCATION OF RELEASE											80													
1	8	0	0	0	40	NA				41												80																
7	8	9	LOSS OF OR DAMAGE TO FACILITY											LOCATION OF RELEASE											80													
1	9	Z	42	NA				43	801009032E											80																		
7	8	9	PUBLICITY											LOCATION OF RELEASE											80													
2	0	N	44	NA				45												80																		
7	8	9	ISSUED											NRC USE ONLY											80													
7	8	9																							80													

NAME OF PREPARER S. D. DELONG

PHONE: 616-465-5901

SEP  
13