

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	5	7	0	3	1	7	8	1	8	0	4	1	5	8	1	9
60	81	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

0 2 | DURING THE PERFORMANCE OF A TEST INSIDE THE UNIT 1 UPPER CONTAINMENT, TEST PERSONNEL

03 | OBSERVED A LARGE PIECE OF HERCULITE SECURELY FASTENED IN A CANOPY FASHION OVER THE

04 | WALKWAY AND A PLASTIC PAIL IN THE VICINITY OF THE LOWER ICE CONDENSER ACCESS DOOR.

05 | THIS IS CONTRARY TO THE SURVEILLANCE REQUIREMENTS OF TECH. SPEC. SECTION 4.5.2.6B. |

0	6	
---	---	--

07 | _____

08

SYSTEM CODE [0] [9] 7 8		CAUSE CODE [Z] [Z] (11) 9 10		CAUSE SUBCODE [A] (12) 11		COMPONENT CODE [Z] [Z] [Z] [Z] [Z] [Z] (14) 12 13 14 15 16 17 18						COMP. SUBCODE [Z] (15) 19		VALVE SUBCODE [Z] (16) 20			
(17) LER/RO REPORT NUMBER [8] [1] 21 22		EVENT YEAR [8] [1] 21 22		SEQUENTIAL REPORT NO. [0] [0] [8] 23 24 25 26		OCCURRENCE CODE [0] [3] 27 28 29		REPORT TYPE [L] 30		REVISION NO. [0] 31 32							
ACTION TAKEN [X] (18) 33		FUTURE ACTION [X] (19) 34		EFFECT ON PLANT [Z] (20) 35		SHUTDOWN METHOD [Z] (21) 36		HOURS (22) [0] [0] [0] [0] 37 38 39 40		ATTACHMENT SUBMITTED [Y] (23) 41		NPRD-4 FORM SUB. [N] (24) 42		PRIME COMP. SUPPLIER [Z] (25) 43		COMPONENT MANUFACTURER [Z] [9] [9] [9] (26) 44 45 46 47	

10 | A REVIEW OF JOB ORDERS WAS PERFORMED IN AN EFFORT TO IDENTIFY THE GROUP OR DEPARTMENT

11 | REQUESTING THE ERECTION OF THIS CANOPY. THIS REVIEW WAS TO NO AVAIL. FURTHER IN-

1 2 | QUIRIES WERE INCONCLUSIVE. DISASSEMBLY OF THE CANOPY AND REMOVAL OF THE BUCKET WERE

1 3 | PERFORMED IN ACCORDANCE WITH THE DIRECTIVES OF AN EMERGENCY JOB ORDER. TO PRECLUDE

14 | THIS EVENT FROM HAPPENING AGAIN, A MEMO WAS ISSUED (SEE ATTACHED SUPPLEMENT).

7 8 9 FACILITY STATUS 30 METHOD OF DISCOVERY 32 DISCOVERY DESCRIPTION 80

1 5 E (28) 1 0 0 (29) NA. B (31) PERFORMANCE PERSONNEL OBSERVATION

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA				

PERSONNEL INJURIES										
NUMBER			DESCRIPTION (41)							
1	8	0	0	0	(40)	NA				

7		8	9	11	12	80
1		2	3	4	5	6
1		9	LOSS OF OR DAMAGE TO FACILITY (43)			
Z		(42)	DESCRIPTION: NA			

	PUBLICITY	(45)	NRC USE ONLY
ISSUED	(44) NA		
2 0			

NRC USE ONLY

8104230682 NAME OF PREPARER ROBERT H. PIEHL

PHONE. 616-465-5901, EXT. 1036

PO 917-926

SUPPLEMENT TO LER # 81-008/03L-0

CAUSE DESCRIPTION

REQUESTING THAT THE REQUIREMENTS RELATIVE TO LOOSE DEBRIS BE RE-EMPHASIZED
TO ALL PLANT AND CONSTRUCTION PERSONNEL.

