

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9308200066 DOC. DATE: 93/08/13 NOTARIZED: NO DOCKET #
FACIL: 50-315, Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH. NAME AUTHOR AFFILIATION
BLIND, A.A. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Retracts LER 92-010 dtd 921223. Util has determined that
cable need not have been protected (wrapped) or surveilled.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1	PD3-1 PD	1
	DEAN, W	1		
INTERNAL:	ACNW	2	AEOD/DOA	1
	AEOD/DSP/TPAB	1	AEOD/ROAB/DSP	2
	NRR/DE/EELB	1	NRR/DE/EMEB	1
	NRR/DORS/OEAB	1	NRR/DRCH/HHFB	1
	NRR/DRCH/HICB	1	NRR/DRCH/HOLB	1
	NRR/DRIL/RPEB	1	NRR/DRSS/PRPB	2
	NRR/DSSA/SPLB	1	NRR/DSSA/SRXB	1
	<u>REG FILE</u> 02	1	RES/DSIR/EIB	1
	RGN3 FILE 01	1		
EXTERNAL:	EG&G BRYCE, J.H	2	L ST LOBBY WARD	1
	NRC PDR	1	NSIC MURPHY, G.A	1
	NSIC POORE, W.	1	NUDOCS FULL TXT	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 30 ENCL ~~30~~ 0

10-4
210

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Place
Bridgman, MI 49106
616 465 5901



August 13, 1993

United States Nuclear Regulatory Commission
Document Control Desk
Rockville, Maryland 20852

Operating Licenses DPR-58
Docket No. 50-315

Document Control Manager:

The purpose of this letter is to retract Licensee Event Report (LER) #50-315 92-010 dated 12/23/92. The LER indicated that we were not in compliance with our technical specifications (TSS) in that one Thermo-lag 330 wrapped cable located in Fire Zone 22 had not been included in the TS surveillance program since September 1990 (installation date).

It has now been determined that the cable need not have been protected (wrapped) or surveilled. The completion/installation of two modifications, 12-2900-B.04 and 12-3053, provided additional Control Room reactor coolant system temperature and pressure indication and were not routed through the affected fire zones. These modifications had the effect of placing Fire Zone 22 into Appendix R Category III.G.1 which would not require cable protection. (See LER #50-316 93-005 for additional details.)

Sincerely,


A. A. Blind
Plant Manager

/sb

Attachment

9308200066 930813
PDR ADCCK 05000315
S PDR

JE27 1/0

USNRC
8-13-93
Page 2

c: J. B. Martin, Region III
E. E. Fitzpatrick
P. A. Barrett
R. F. Kroeger
W. E. Walters - Ft. Wayne
NRC Resident Inspector
B. A. Wetzel - NRC
M. R. Padgett
G. Charnoff, Esq.
D. Hahn
INPO
S. J. Brewer
B. A. Svensson