

ATTACHMENT 1 TO AEP:NRG:0659AB

CURRENT TECHNICAL SPECIFICATION PAGES
WITH CHANGES MARKED

9607290193 960722
PDR ADDCK 05000315
P PDR

ADMINISTRATIVE CONTROLS

6.1 RESPONSIBILITY

6.1.1 The Plant Manager shall be responsible for overall facility operation and shall delegate in writing the succession to this responsibility during his absence.

6.1.2 The Shift Supervisor (or during his absence from the control room complex, a designated individual) shall be responsible for the control room command function. A management directive to this effect signed by the Vice President - Nuclear Operations shall be reissued to all station personnel on an annual basis.

6.2 ORGANIZATION

ONSITE AND OFFSITE ORGANIZATIONS

6.2.1 Onsite and offsite organizations shall be established for unit operation and corporate management, respectively. The onsite and offsite organizations shall include the positions for activities affecting the safety of the nuclear power plant.

- a. Lines of authority, responsibility, and communication shall be established and defined for the highest management level through intermediate levels to and including all operating organization positions. These relationships shall be documented and updated, as appropriate, in the form of organizational charts. These organizational charts will be documented in the UFSAR and updated in accordance with 10 CFR 50.71(e).
- b. The Plant Manager shall be responsible for overall unit safe operation and shall have control over those onsite activities necessary for safe operation and maintenance of the plant.
- c. The Vice President - Nuclear Operations shall have corporate responsibility for overall plant nuclear safety and shall take any measures needed to ensure acceptable performance of the staff in operating, maintaining, and providing technical support to the plant to ensure nuclear safety.
- d. The individuals who train the operating staff and those who carry out health physics and quality assurance functions may report to the appropriate onsite manager; however, they shall have sufficient organizational freedom to ensure their independence from operating pressures.

THIS WAS MOVED TO PAGE 6-2

FACILITY STAFF

6.2.2 The Facility organization shall be subject to the following:

- a. Each on duty shift shall be composed of at least the minimum shift crew composition shown in Table 6.2-1.

ADMINISTRATIVE CONTROLS

- b. At least one licensed Operator shall be in the control room when fuel is in the reactor. In addition, while the unit is in Mode 1, 2, 3, or 4, at least one licensed Senior Operator shall be in the control room.
- c. An individual* qualified in radiation protection procedures shall be on site when fuel is in the reactor.
- d. All CORE ALTERATIONS shall be directly supervised by a licensed Senior Operator trained or qualified in refueling and CORE ALTERATIONS (SO-CA) who has no other concurrent responsibilities during this operation.
- e. A site fire brigade of at least 5 members* shall be maintained onsite at all times. The fire brigade shall not include 3 members of the minimum shift crew necessary for safe shutdown of the unit or any personnel required for other essential functions during a fire emergency.
- f. The amount of overtime worked by plant staff members performing safety-related functions must be limited in accordance with NRC Policy Statement on working hours (Generic Letter 82-12).
- g. The Shift Supervisor, Assistant Shift Supervisor, and Unit Supervisor shall hold a Senior Operator License.
- h. The Operations Superintendent must hold or have held a Senior Operator License at Cook Nuclear Plant or a similar reactor, ~~and one mid-level Operations Production Supervisor shall hold a current Senior Operator License.~~ or have been certified for equivalent senior operator knowledge. If the Operations Superintendent does not hold a Senior Operator License, then ^{active (v. shift)} operations middle manager shall hold a Senior Operator License for the purposes of directing operational activities.

*The individual qualified in radiation protection procedures and the composition of the fire brigade may be less than the minimum requirements for a period of time not to exceed 2 hours, in order to accommodate unexpected absence provided immediate action is taken to fill the required positions.

ADMINISTRATIVE CONTROLS

6.3 FACILITY STAFF QUALIFICATIONS

6.3.1 Each member of the facility staff shall meet or exceed the minimum qualifications of ANSI N18.1-1971 for comparable positions, except for (1) the Plant Radiation Protection Manager, who shall meet or exceed qualifications of Regulatory Guide 1.8, September 1975, (2) the Shift Technical Advisor, who shall have a bachelor's degree or equivalent in a scientific or engineering discipline with specific training in plant design, and response and analysis of the plant for transients and accidents and, (3) the Operations Superintendent, who must hold or have held a Senior Operator License as specified in Section 6.2.2.h.

6.4 TRAINING

6.4.1 A retraining and replacement training program for the facility staff shall be maintained under the direction of the Training Manager and shall meet or exceed the requirements and recommendations of Section 5.5 of ANSI N18.1-1971 and 10 CFR Part 55.

6.5 REVIEW AND AUDIT

6.5.1 PLANT NUCLEAR SAFETY REVIEW COMMITTEE (PNSRC)

FUNCTION

6.5.1.1 The PNSRC shall function to advise the Site Vice President/Plant Manager, or designee, on all matters related to nuclear safety.

COMPOSITION

6.5.1.2 The PNSRC shall be composed of Assistant Plant Managers, Department Superintendents, or supervisory personnel reporting directly to the Site Vice President/Plant Manager, Assistant Plant Managers or Department Superintendents. The membership shall represent the functional areas of the plant, including, but not limited to Operations, Technical Support, Licensing, Maintenance and Radiation Protection.

The PNSRC membership shall consist of at least one individual from each of the areas designated. All members, including the Chairman and his alternates, the members and their alternates, shall be designated by the Site Vice President/Plant Manager.

PNSRC members and alternates shall meet or exceed the minimum qualifications of ANSI N18.1-1971 Section 4.4 for comparable positions. The nuclear power plant operations individual shall meet the qualifications of Section 4.2.2 of ANSI N18.1-1971 except for the requirement to hold a current Senior Operator License. The operations individual must hold or have held a Senior Operator License, at Cook Nuclear Plant or a similar reactor. The maintenance individual shall meet the qualifications of Section 4.2.3 of ANSI N18.1-1971.

or have been certified for
equivalent senior operator knowledge

ADMINISTRATIVE CONTROLS

6.1 RESPONSIBILITY

6.1.1 The Plant Manager shall be responsible for overall facility operation and shall delegate in writing the succession to this responsibility during his absence.

6.1.2 The Shift Supervisor (or during his absence from the control room complex, a designated individual) shall be responsible for the control room command function. A management directive to this effect signed by the Vice President - Nuclear Operations shall be reissued to all station personnel on an annual basis.

6.2 ORGANIZATION

ONSITE AND OFFSITE ORGANIZATIONS

6.2.1 Onsite and offsite organizations shall be established for unit operation and corporate management, respectively. The onsite and offsite organizations shall include the positions for activities affecting the safety of the nuclear power plant.

- a. Lines of authority, responsibility, and communication shall be established and defined for the highest management level through intermediate levels to and including all operating organization positions. These relationships shall be documented and updated, as appropriate, in the form of organizational charts. These organizational charts will be documented in the UFSAR and updated in accordance with 10 CFR 50.71(e).
- b. The Plant Manager shall be responsible for overall unit safe operation and shall have control over those onsite activities necessary for safe operation and maintenance of the plant.
- c. The Vice President - Nuclear Operations shall have corporate responsibility for overall plant nuclear safety and shall take any measures needed to ensure acceptable performance of the staff in operating, maintaining, and providing technical support to the plant to ensure nuclear safety.
- d. The individuals who train the operating staff and those who carry out health physics and quality assurance functions may report to the appropriate onsite manager; however, they shall have sufficient organizational freedom to ensure their independence from operating pressures.

FACILITY STAFF

THIS WAS MOVED TO PAGE 6-2

6.2.2 The Facility organization shall be subject to the following:

- a. Each on duty shift shall be composed of at least the minimum shift crew composition shown in Table 6.2-1.

ADMINISTRATIVE CONTROLS

- b. At least one licensed Operator shall be in the control room when fuel is in the reactor. In addition, while the unit is in Mode 1, 2, 3, or 4, at least one licensed Senior Operator shall be in the control room.
- c. An individual* qualified in radiation protection procedures shall be on site when fuel is in the reactor.
- d. All CORE ALTERATIONS shall be directly supervised by a licensed Senior Operator trained or qualified in refueling and CORE ALTERATIONS (SO-CA) who has no other concurrent responsibilities during this operation.
- e. A site fire brigade of at least 5 members* shall be maintained onsite at all times. The fire brigade shall not include 3 members of the minimum shift crew necessary for safe shutdown of the unit or any personnel required for other essential functions during a fire emergency.
- f. The amount of overtime worked by plant staff members performing safety-related functions must be limited in accordance with NRC Policy Statement on working hours (Generic Letter 82-12).
- g. The Shift Supervisor, Assistant Shift Supervisor, and Unit Supervisor shall hold a Senior Operator License.
- h. The Operations Superintendent must hold or have held a Senior Operator License at Cook Nuclear Plant or a similar reactor, and ~~one mid-level Operations Production Supervisor shall hold a current Senior Operator License.~~ or have been certified for equivalent senior operator knowledge. If the Operations Superintendent does not hold a Senior Operator License, then ^(S.M.M.) ~~an~~ operations middle manager shall hold a Senior Operator License for the purposes of directing operational activities.

*The individual qualified in radiation protection procedures and the composition of the fire brigade may be less than the minimum requirements for a period of time not to exceed 2 hours, in order to accommodate unexpected absence provided immediate action is taken to fill the required positions.

ADMINISTRATIVE CONTROLS

6.3 FACILITY STAFF QUALIFICATIONS

6.3.1 Each member of the facility staff shall meet or exceed the minimum qualifications of ANSI N18.1-1971 for comparable positions, except for (1) the Plant Radiation Protection Manager, who shall meet or exceed qualifications of Regulatory Guide 1.8, September 1975, (2) the Shift Technical Advisor, who shall have a bachelor's degree or equivalent in a scientific or engineering discipline with specific training in plant design, and response and analysis of the plant for transients and accidents and, (3) the Operations Superintendent who must hold or have held a Senior Operator License as specified in Section 6.2.2.h.

6.4 TRAINING

6.4.1 A retraining and replacement training program for the facility staff shall be maintained under the direction of the Training Manager and shall meet or exceed the requirements and recommendations of Section 5.5 of ANSI N18.1-1971 and 10 CFR Part 55.

6.5 REVIEW AND AUDIT

6.5.1 PLANT NUCLEAR SAFETY REVIEW COMMITTEE (PNSRC)

FUNCTION

6.5.1.1 The PNSRC shall function to advise the Site Vice President/Plant Manager, or designee, on all matters related to nuclear safety.

COMPOSITION

6.5.1.2 The PNSRC shall be composed of Assistant Plant Managers, Department Superintendents, or supervisory personnel reporting directly to the Site Vice President/Plant Manager, Assistant Plant Managers or Department Superintendents. The membership shall represent the functional areas of the plant, including, but not limited to Operations, Technical Support, Licensing, Maintenance and Radiation Protection.

The PNSRC membership shall consist of at least one individual from each of the areas designated. All members, including the Chairman and his alternates, the members and their alternates, shall be designated by the Site Vice President/Plant Manager.

PNSRC members and alternates shall meet or exceed the minimum qualifications of ANSI N18.1-1971 Section 4.4 for comparable positions. The nuclear power plant operations individual shall meet the qualifications of Section 4.2.2 of ANSI N18.1-1971 except for the requirement to hold a current Senior Operator License. The operations individual must hold or have held a Senior Operator License at Cook Nuclear Plant or a similar reactor. The maintenance individual shall meet the qualifications of Section 4.2.3 of ANSI N18.1-1971.

or have been certified for equivalent senior operator knowledge

ATTACHMENT 2 TO AEP:NRG:0659AB

PROPOSED TECHNICAL SPECIFICATION PAGES

6.0 ADMINISTRATIVE CONTROLS

6.1 RESPONSIBILITY

- 6.1.1 The Plant Manager shall be responsible for overall facility operation and shall delegate in writing the succession to this responsibility during his absence.
- 6.1.2 The Shift Supervisor (or during his absence from the control room complex, a designated individual) shall be responsible for the control room command function. A management directive to this effect signed by the Vice President - Nuclear Operations shall be reissued to all station personnel on an annual basis.

6.2 ORGANIZATION

ONSITE AND OFFSITE ORGANIZATIONS

- 6.2.1 Onsite and offsite organizations shall be established for unit operation and corporate management, respectively. The onsite and offsite organizations shall include the positions for activities affecting the safety of the nuclear power plant.
 - a. Lines of authority, responsibility, and communication shall be established and defined for the highest management level through intermediate levels to and including all operating organization positions. These relationships shall be documented and updated, as appropriate, in the form of organizational charts. These organizational charts will be documented in the UFSAR and updated in accordance with 10 CFR 50.71(e).
 - b. The Plant Manager shall be responsible for overall unit safe operation and shall have control over those onsite activities necessary for safe operation and maintenance of the plant.
 - c. The Vice President - Nuclear Operations shall have corporate responsibility for overall plant nuclear safety and shall take any measures needed to ensure acceptable performance of the staff in operating, maintaining, and providing technical support to the plant to ensure nuclear safety.
 - d. The individuals who train the operating staff and those who carry out health physics and quality assurance functions may report to the appropriate onsite manager; however, they shall have sufficient organizational freedom to ensure their independence from operating pressures.

6.0 ADMINISTRATIVE CONTROLS

6.2 ORGANIZATION (Continued)

FACILITY STAFF

6.2.2 The Facility organization shall be subject to the following:

- a. Each on duty shift shall be composed of at least the minimum shift crew composition shown in Table 6.2-1.
- b. At least one licensed Operator shall be in the control room when fuel is in the reactor. In addition, while the unit is in Mode 1, 2, 3, or 4, at least one licensed Senior Operator shall be in the control room.
- c. An individual* qualified in radiation protection procedures shall be on site when fuel is in the reactor.
- d. All CORE ALTERATIONS shall be directly supervised by a licensed Senior Operator trained or qualified in refueling and CORE ALTERATIONS (SO-CA) who has no other concurrent responsibilities during this operation.
- e. A site fire brigade of at least 5 members* shall be maintained onsite at all times. The fire brigade shall not include 3 members of the minimum shift crew necessary for safe shutdown of the unit or any personnel required for other essential functions during a fire emergency.
- f. The amount of overtime worked by plant staff members performing safety-related functions must be limited in accordance with NRC Policy Statement on working hours (Generic Letter 82-12).
- g. The Shift Supervisor, Assistant Shift Supervisor, and Unit Supervisor shall hold a Senior Operator License.
- h. The Operations Superintendent must hold or have held a Senior Operator License at Cook Nuclear Plant or a similar reactor, or have been certified for equivalent senior operator knowledge. If the Operations Superintendent does not hold a Senior Operator License, then a line (v. staff) operations middle manager shall hold a Senior Operator License for the purposes of directing operational activities.

* The individual qualified in radiation protection procedures and the composition of the fire brigade may be less than the minimum requirements for a period of time not to exceed 2 hours, in order to accommodate unexpected absence provided immediate action is taken to fill the required positions.

6.0 ADMINISTRATIVE CONTROLS

6.3 FACILITY STAFF QUALIFICATIONS

- 6.3.1 Each member of the facility staff shall meet or exceed the minimum qualifications of ANSI N18.1-1971 for comparable positions, except for (1) the Plant Radiation Protection Manager, who shall meet or exceed qualifications of Regulatory Guide 1.8, September 1975, (2) the Shift Technical Advisor, who shall have a bachelor's degree or equivalent in a scientific or engineering discipline with specific training in plant design, and response and analysis of the plant for transients and accidents and, (3) the Operations Superintendent, who must hold or have held a Senior Operator License as specified in Section 6.2.2.h.

6.4 TRAINING

- 6.4.1 A retraining and replacement training program for the facility staff shall be maintained under the direction of the Training Manager and shall meet or exceed the requirements and recommendations of Section 5.5 of ANSI N18.1-1971 and 10 CFR Part 55.

6.5 REVIEW AND AUDIT

6.5.1 PLANT NUCLEAR SAFETY REVIEW COMMITTEE (PNSRC)

FUNCTION

- 6.5.1.1 The PNSRC shall function to advise the Site Vice President/Plant Manager, or designee, on all matters related to nuclear safety.

COMPOSITION

- 6.5.1.2 The PNSRC shall be composed of Assistant Plant Managers, Department Superintendents, or supervisory personnel reporting directly to the Site Vice President/Plant Manager, Assistant Plant Managers or Department Superintendents. The membership shall represent the functional areas of the plant, including, but not limited to Operations, Technical Support, Licensing, Maintenance and Radiation Protection.

The PNSRC membership shall consist of at least one individual from each of the areas designated. All members, including the Chairman and his alternates, the members and their alternates, shall be designated by the Site Vice President/Plant Manager.

PNSRC members and alternates shall meet or exceed the minimum qualifications of ANSI N18.1-1971 Section 4.4 for comparable positions. The nuclear power plant operations individual shall meet the qualifications of Section 4.2.2 of ANSI N18.1-1971 except for the requirement to hold a current Senior Operator License. The operations individual must hold or have held a Senior Operator License or have been certified for equivalent senior operator knowledge at Cook Nuclear Plant or a similar reactor. The maintenance individual shall meet the qualifications of Section 4.2.3 of ANSI N18.1-1971.

6.0 ADMINISTRATIVE CONTROLS

6.1 RESPONSIBILITY

- 6.1.1 The Plant Manager shall be responsible for overall facility operation and shall delegate in writing the succession to this responsibility during his absence.
- 6.1.2 The Shift Supervisor (or during his absence from the control room complex, a designated individual) shall be responsible for the control room command function. A management directive to this effect signed by the Vice President - Nuclear Operations shall be reissued to all station personnel on an annual basis.

6.2 ORGANIZATION

ONSITE AND OFFSITE ORGANIZATIONS

- 6.2.1 Onsite and offsite organizations shall be established for unit operation and corporate management, respectively. The onsite and offsite organizations shall include the positions for activities affecting the safety of the nuclear power plant.
- a. Lines of authority, responsibility, and communication shall be established and defined for the highest management level through intermediate levels to and including all operating organization positions. These relationships shall be documented and updated, as appropriate, in the form of organizational charts. These organizational charts will be documented in the UFSAR and updated in accordance with 10 CFR 50.71(e).
 - b. The Plant Manager shall be responsible for overall unit safe operation and shall have control over those onsite activities necessary for safe operation and maintenance of the plant.
 - c. The Vice President - Nuclear Operations shall have corporate responsibility for overall plant nuclear safety and shall take any measures needed to ensure acceptable performance of the staff in operating, maintaining, and providing technical support to the plant to ensure nuclear safety.
 - d. The individuals who train the operating staff and those who carry out health physics and quality assurance functions may report to the appropriate onsite manager; however, they shall have sufficient organizational freedom to ensure their independence from operating pressures.

6.0 ADMINISTRATIVE CONTROLS

6.2 ORGANIZATION (Continued)

FACILITY STAFF

6.2.2 The Facility organization shall be subject to the following:

- a. Each on duty shift shall be composed of at least the minimum shift crew composition shown in Table 6.2-1.
- b. At least one licensed Operator shall be in the control room when fuel is in the reactor. In addition, while the unit is in Mode 1, 2, 3, or 4, at least one licensed Senior Operator shall be in the control room.
- c. An individual* qualified in radiation protection procedures shall be on site when fuel is in the reactor.
- d. All CORE ALTERATIONS shall be directly supervised by a licensed Senior Operator trained or qualified in refueling and CORE ALTERATIONS (SO-CA) who has no other concurrent responsibilities during this operation.
- e. A site fire brigade of at least 5 members* shall be maintained onsite at all times. The fire brigade shall not include 3 members of the minimum shift crew necessary for safe shutdown of the unit or any personnel required for other essential functions during a fire emergency.
- f. The amount of overtime worked by plant staff members performing safety-related functions must be limited in accordance with NRC Policy Statement on working hours (Generic Letter 82-12).
- g. The Shift Supervisor, Assistant Shift Supervisor, and Unit Supervisor shall hold a Senior Operator License.
- h. The Operations Superintendent must hold or have held a Senior Operator License at Cook Nuclear Plant or a similar reactor, or have been certified for equivalent senior operator knowledge. If the Operations Superintendent does not hold a Senior Operator License, then a line (v. staff) operations middle manager shall hold a Senior Operator License for the purposes of directing operational activities.

* The individual qualified in radiation protection procedures and the composition of the fire brigade may be less than the minimum requirements for a period of time not to exceed 2 hours, in order to accommodate unexpected absence provided immediate action is taken to fill the required positions.

6.0 ADMINISTRATIVE CONTROLS

6.3 FACILITY STAFF QUALIFICATIONS

- 6.3.1 Each member of the facility staff shall meet or exceed the minimum qualifications of ANSI N18.1-1971 for comparable positions, except for (1) the Plant Radiation Protection Manager, who shall meet or exceed qualifications of Regulatory Guide 1.8, September 1975, (2) the Shift Technical Advisor, who shall have a bachelor's degree or equivalent in a scientific or engineering discipline with specific training in plant design, and response and analysis of the plant for transients and accidents and, (3) the Operations Superintendent, who must hold or have held a Senior Operator License as specified in Section 6.2.2.h.

6.4 TRAINING

- 6.4.1 A retraining and replacement training program for the facility staff shall be maintained under the direction of the Training Manager and shall meet or exceed the requirements and recommendations of Section 5.5 of ANSI N18.1-1971 and 10 CFR Part 55.

6.5 REVIEW AND AUDIT

6.5.1 PLANT NUCLEAR SAFETY REVIEW COMMITTEE (PNSRC)

FUNCTION

- 6.5.1.1 The PNSRC shall function to advise the Site Vice President/Plant Manager, or designee, on all matters related to nuclear safety.

COMPOSITION

- 6.5.1.2 The PNSRC shall be composed of Assistant Plant Managers, Department Superintendents, or supervisory personnel reporting directly to the Site Vice President/Plant Manager, Assistant Plant Managers or Department Superintendents. The membership shall represent the functional areas of the plant, including, but not limited to Operations, Technical Support, Licensing, Maintenance and Radiation Protection.

The PNSRC membership shall consist of at least one individual from each of the areas designated. All members, including the Chairman and his alternates, the members and their alternates, shall be designated by the Site Vice President/Plant Manager.

PNSRC members and alternates shall meet or exceed the minimum qualifications of ANSI N18.1-1971 Section 4.4 for comparable positions. The nuclear power plant operations individual shall meet the qualifications of Section 4.2.2 of ANSI N18.1-1971 except for the requirement to hold a current Senior Operator License. The operations individual must hold or have held a Senior Operator License or have been certified for equivalent senior operator knowledge at Cook Nuclear Plant or a similar reactor. The maintenance individual shall meet the qualifications of Section 4.2.3 of ANSI N18.1-1971.