

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8910050047 DOC. DATE: 89/09/29 NOTARIZED: NO DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
 AUTH. NAME AUTHOR AFFILIATION  
 ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Responds to SALP 8 Board rept for period Mar 1988 - June 1989.

DISTRIBUTION CODE: IE40D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
 TITLE: Systematic Assessment of Licensee Performance (SALP) Report

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1 0	PD3-1 PD	1 1
	GIITTER, J.	1 1		
INTERNAL:	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	COMMISSION	5 5	DEDRO	1 1
	NRR SHANKMAN, S	1 1	NRR/DLPQ/HFB 10	1 1
	NRR/DLPQ/PEB 10	1 1	NRR/DOEA/EAB 11	1 1
	NRR/DREP/EPB 10	1 1	NRR/DREP/RPB 10	1 1
	NRR/DRIS DIR 9A	1 1	NRR/DRIS/SGB 9D	2 2
	NRR/DRIS/SIB 9A	1 1	NRR/PMAS/ILRB12	1 1
	NUDOCS-ABSTRACT	1 1	OE DIR	1 1
	OGC/HDS1	1 1	<u>REG FILE</u> 02	1 1
	RGN3 FILE 01	1 1		
EXTERNAL:	L ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 30



AEP:NRC:0973I

Donald C. Cook Nuclear Plant Units 1 and 2  
Docket Nos. 50-315 and 50-316  
License Nos. DPR-58 and DPR-74  
RESPONSE TO SYSTEMATIC ASSESSMENT OF LICENSEE  
PERFORMANCE (SALP) 8 BOARD REPORT

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Attn: A. B. Davis

September 29, 1989

Dear Mr. Davis:

Thank you for the opportunity on September 26, 1989, to discuss the SALP 8 Board Report for the Donald C. Cook Nuclear Generating Plant, covering the period from March 1, 1988, through June 30, 1989. We have taken note of the weaknesses you cited and will rigorously pursue corrective actions in these areas.

It should be noted, as discussed during our meeting, that there are no plans at this time to create a new engineering group onsite that reports to corporate engineering as stated on page 20 of the report. However, a corporate reorganization has taken place that consolidates all of the designers who work on Cook Nuclear Plant issues into one group within the Design Department. Prior to this reorganization, these designers, although knowledgeable about Cook Nuclear Plant, were occasionally called upon to work on issues involving other AEP System plants. These individuals are now dedicated exclusively to Cook Nuclear Plant. This follows a recent, similar consolidation of mechanical and electrical engineers supporting Cook Nuclear Plant into a new, integrated Nuclear Engineering Department. We believe that this increased focus on Cook Nuclear Plant within the Service Corporation will result in better design implementation on site, and more effective engineering support.

IE40  
1/1



Mr. A. B. Davis

-2-

AEP:NRC:0973I

This document has been prepared following Corporate procedures that incorporate a reasonable set of controls to ensure its accuracy and completeness prior to signature by the undersigned.

Sincerely,



M. P. Alexich  
Vice President

ldp

cc: D. H. Williams, Jr.  
A. A. Blind - Bridgman  
R. C. Callen  
G. Charnoff  
NRC Resident Inspector - Bridgman  
NFEM Section Chief