

C
A
T
E
G
O
R
Y
1
D
O
C
U
M
E
N
T

$$2 + 4$$
$$2 + 4$$

**D
O
C
U
M
E
N
T**

RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
PD3-3 PD	LTTR	ENCL	STANG, J	LTTR	ENCL
INTERNAL: AEOD/SPD/RAB	2	2	AEOD/SPD/RRAB	1	1
FILE CENTER	1	1	NRR/DE/ECGB	1	1
NRR/DE/EELB	1	1	NRR/DE/EMEB	1	1
NRR/DRCH/HICB	1	1	NRR/DRCH/HOHB	1	1
NRR/DRCH/HQMB	1	1	NRR/DRPM/PECB	1	1
NRR/DSSA/SPLB	1	1	RES/DET/EIB	1	1
RGN3 FILE 01	1	1			
EXTERNAL: L ST LOBBY WARD	1	1	LITCO BRYCE, J H	1	1
NOAC POORE, W.	1	1	NOAC QUEENER, DS	1	1
NRC PDR	1	1	NUDOCS FULL TXT	1	1

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

AO

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



December 3, 1998

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/98-046-00, "Auxiliary Feedwater System Unable to Meet Design Flow Requirements During Special Test."

The following commitments have been identified:

- The Auxiliary Feedwater System design will be modified to ensure the system is capable of maintaining design flow rate while taking suction from the Emergency Service Water System. This has been identified as a restart issue.
- The Engineering Issues Review Group will assess the scope and quality of actions being taken to address system, structure, and component performance including operability, design and licensing basis issues as they relate to identified engineering issues.
- The Engineering Issues Review Group will review the results of the Auxiliary Feedwater System SSFI to ensure that lessons learned from this inspection have been identified and factored into the restart strategies and other corrective actions taken to address engineering issues.

Sincerely,

J. R. Sampson
Site Vice President

/mbd
Attachment

9812090135 981203
PDR ADOCK 05000315
S PDR

c: J. L. Caldwell (Acting), Region III
R. P. Powers
P. A. Barrett
J. B. Kingseed
R. Whale
D. Hahn
Records Center, INPONRC
Resident Inspector