

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SUBJECT: Forwards LER 99-001-00 re discovery that GE HFA relays installed in EDGs may not meet seismic qualification. Commitments made by util, listed.

NOTES :-

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD3-3 PD		1	1		STANG, J		1	1
INTERNAL:	AEOD/SPD/RAB		2	2		AEOD/SPD/RRAB		1	1
	FILE CENTER		1	1		NRR/DRCH/HOHB		1	1
	NRR/DRCH/HQMB		1	1		NRR/DRPM/PECB		1	1
	NRR/DSSA/SPLB		1	1		RES/DET/EIB		1	1
	RGN3 FILE 01		1	1					
EXTERNAL:	L ST LOBBY WARD		1	1		LITCO BRYCE, J H		1	1
	NOAC POORE, W.		1	1		NOAC QUEENER, DS		1	1
	NRC PDR		1	1		NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 18

404



February 10, 1999

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:


In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/99-001-00, "General Electric HFA Relays Installed in Emergency Diesel Generators May Not Meet Seismic Qualification."

The following commitments have been identified in this submittal:

- Upon completion of the HFA relay inspection, those relays that are determined to be non-compliant with vendor specifications will be evaluated for seismic performance.
- Design changes to the nine EDG relays identified will be implemented prior to the EDGs being declared operable.
- Additional evaluations are required for the effect on equipment in other plant operating modes.
- Results of the root cause investigation will be provided in an update to this LER, including information regarding additional corrective actions and/or preventive actions.

Sincerely,


J. R. Sampson
Site Vice President

/mbd
Attachment

190040

9902220015 990210
PDR ADOCK 05000315
S PDR

11
TE22

c: J. E. Dyer, Region III
R. P. Powers
P. A. Barrett
D. F. Kunsemiller
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector