

A002

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-251 DOC DATE: 780930
 RECIPIENT: O'Reilly, J.P. NOIR2 ACCESSION NBR: 7810120050
 ORIGINATOR: Schmidt, A.D. EUTFPL COPIES RECEIVED:
 COMPANY NAME: Florida Pwr & Light Co. LTR 3 ENCL 3
 SUBJECT: SIZE: 1 + 1

Forwards LER#78-009/03L-0: 20 safety related hydraulic snubbers failed functional tests due to control block poppet valve & relief valve malfunctions & excessive main cylinder wear. Hydraulic type replaced w/mechanical type snubbers.

DISTRIBUTION CODE: A002
 DISTRIBUTION TITLE:
 INCIDENT REPORTS

NAME	ENCL?	FOR ACTION
BR CHIEF	W/4 ENCL	D. Eisenhower
REG FILE	W/ENCL	ORB#1 BC
NRC PDR	W/ENCL	M. Grotenhuis
I & E	W/2 ENCL	ORB#1 LA
MIPC	W/3 ENCL	
I & C SYSTEMS BR	W/ENCL	
EMERGENCY PLAN BR	W/ENCL	
NOVAK/CHECK	W/ENCL	
EEB	W/ENCL	
AD FOR ENG	W/ENCL	
PLANT SYSTEMS BR	W/ENCL	
HANAUER	W/ENCL	
AD FOR PLANT SYSTEMS	W/ENCL	
AD FOR SYS & PROJ	W/ENCL	
REACTOR SAFETY BR	W/ENCL	
ENGINEERING BR	W/ENCL	
VOLLMER/BUNCH	W/ENCL	
KREGER/J. COLLINS	W/ENCL	
POWER SYS BR	W/ENCL	
K SEYFRIT/IE	W/ENCL	
LPDR	W/ENCL	
NSIC	W/ENCL	
ACRS	W/16 ENCL	

TOTAL NUMBER OF COPIES REQUIRED:

LTR
 ENCL

44
 44

NOTES:

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-78-9
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: August 31, 1978

TECHNICAL SPECIFICATION 4.14.4
HYDRAULIC SNUBBERS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30 day notification of the subject occurrence.

Very truly yours,

C. D. Woody
A. D. Schmidt
Vice President
Power Resources

WAK/dep

Attachment

cc: Robert Lowenstein, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

781012 005P.