

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-251 Turkey Pt #4
 RECIPIENT: Stello, V.
 ORIGINATOR: Uhrig, R.E.
 COMPANY: F1 Pwr & Light
 SUBJECT: _____

DOC DATE: 781010
 ACCESSION NBR: 7810170191
 COPIES RECEIVED: _____
 LTR 3 ENCL 3
 SIZE: 3 + 89

Fifth Year Surveillance Rept of containment struct post-tensioning sys.
Concludes that sys is performing w/in limits set by design criteria &
specs. Includes wire testing & analysis of sheath filler.

SGS RPT

DISTRIBUTION CODE: A001

DISTRIBUTION TITLE:

GENERAL DISTRIBUTION FOR AFTER ISSUANCE OF OPERATING LICENSE;

NAME	ENCL?
BR CHIEF	W/7 ENCL
REG FILE	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
OELD	LTR ONLY
HANAUER	W/ENCL
CORE PERFORMANCE BR	W/ENCL
AD FOR SYS & PROJ	W/ENCL
ENGINEERING BR	W/ENCL
REACTOR SAFETY BR	W/ENCL
PLANT SYSTEMS BR	W/ENCL
EER	W/ENCL
EFFLUENT TREAT SYS	W/ENCL
J MCGOUGH	W/ENCL
LPDR	W/ENCL
TERA	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

TOTAL NUMBER OF COPIES REQUIRED:

LTR	40
ENCL	39

NOTES:

OCT 19 1978



FLORIDA POWER & LIGHT COMPANY

October 10, 1978
L-78-332

Director of Nuclear Reactor Regulation
Attention: Mr. Victor Stello, Director
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Stello:

Re: Turkey Point Unit No.4
Docket No. 50-251
Containment Structure Post-Tensioning System
Fifth Year Surveillance Report

Enclosed is the subject report prepared for us by our architect engineer. Twenty (20) copies are transmitted herewith pursuant to Technical Specification 6.9.3.

Additionally, our review of the Fifth Year Surveillance Report has indicated a minor error in the Third Year Surveillance Report which was submitted by letter dated August 25, 1975 (L-75-404). Twenty (20) copies of the two revised pages of the Third Year Surveillance Report are enclosed.

Very truly yours,

Robert E. Uhrig
Vice President

REU/WAK/dep

Attachment

cc: Mr. James P. O'Reilly, Region II
Robert Lowenstein, Esquire

REGULATORY DOCKET FILE COPY

