

CONTROL BLOCK: | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CNT  
 0 1  
 7 3

REPORT SOURCE 1 L 5 0 1 5 1 0 1 0 1 2 5 1 1 7 0 1 9 2 1 7 1 7 1 8 3 1 1 0 1 1 1 1 7 1 8 9  
 40 41 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | Prior to startup for Unit 4 for Cycle 5 operation, an audit of the Cycle 5 |  
013 | core configuration revealed that fuel assembly N-04 had been loaded in core |  
014 | position F-14. The NSSS vendor's base core loading pattern called for fuel |  
015 | assembly N-07 to be loaded in core position F-14. Due to the similarities |  
016 | between assemblies N-04 and N-07, the substitution had no adverse affect |  
017 | on the public health and safety. This is the first occurrence of this |  
018 | type.

SYSTEM CODE R 9		CAUSE CODE D 11		CAUSE SUBCODE Z 12		COMPONENT CODE F U E L I X X 14				COMP. SUBCODE Z 15		VALVE SUBCODE Z 16					
EVENT YEAR 7 8		SEQUENTIAL REPORT NO. 0 1 1 2		OCCURRENCE CODE 0 1		REPORT TYPE T		REVISION NO. 0									
ACTION TAKEN X 18		FUTURE ACTION Z 19		EFFECT ON PLANT C 20		SHUTDOWN METHOD Z 21		HOURS 0 0 3 6		ATTACHMENT SUBMITTED N 23		APPROD. ACORN SUB. N 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER W 1 1 2 1 0 1 25	

**CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)**

110 Substitution occurred as a result of misreading a European style 7 as a 4  
111 on the base core loading pattern as transmitted from the NSSS vendor.  
112 Analyses, evaluations, and reviews by FPI and the vendor concluded that  
113 the Cycle 5 reload safety evaluation remains valid. Validation of the  
114 core loading pattern received from the NSSS vendor will prevent recurrence.

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30																																																																																											
FACILITY STATUS																														% POWER																														OTHER STATUS																														METHOD OF DISCOVERY																														DISCOVERY DESCRIPTION																													
H																														101010																														NA																														B																														Audit																													

ACTIVITY CONTENT RELEASED OF RELEASE		AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1	5	NA	NA

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	37	Z	23	NA		

PERSONNEL INJURIES			30	
11	12	13		
NUMBER	DESCRIPTION	(41)		
113	NA	(60)		

7	3	11	12	30
LOSS OF OR DAMAGE TO FACILITY (43)				
TYPE		DESCRIPTION		
1		NA		

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
PUBLISHER										NA													
ISSUED										NRC USE ONLY													
DESCRIPTION										NA													

2 1 N 54 NA 48 53 10

NAME OF PREPARER M. A. Schoppman PHONE: (305) 552-3802

7810200117



100