

A002

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-251 TURKEY PT 4  
RECIPIENT: OREILLY, J.P.  
ORIGINATOR: SCHMIDT, A.D.  
COMPANY NAME: EL PWR & LIGHT  
SUBJECT:

DOC DATE: 781013  
ACCESSION NBR: 7810230250  
COPIES RECEIVED:  
LTR 1 ENCL 1  
SIZE: 1+2

LER#78-011/03L-0 on 780920: Preventive maintenance checks of MSIV's solenoid valves revealed defective coils. Failure of coils caused by high temp & moisture in area. Preventive maintenance re solenoid coils is planned.

DISTRIBUTION CODE: A002  
DISTRIBUTION TITLE:  
INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
EMERGENCY PLAN BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
VOLLMEYER/BUNCH	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
K SEYFRIT/IE	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

TOTAL NUMBER OF COPIES REQUIRED:

LTR  
ENCL

44  
44

OCT 25 1978

NOTES:



October 13, 1978

PRN-LI-78-298

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-78-11  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: SEPTEMBER 20, 1978

MSIV SOLENOID VALVES

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30-day notification of the subject occurrence.

Very truly yours,

*C. D. Schmidt*  
A. D. Schmidt  
Vice President  
Power Resources

WAK/cpc

Attachment

cc: Robert Lowenstein, Esquire  
Director, Office of Inspection and Enforcement (30)  
Director, Office of Management Information and  
Program Control (3)

REGULATORY DOCKET FILE COPY

7810230250

A002  
15/11