

A002

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 05000251 TURKEY PT 4
RECIPIENT: O'REILLY, J.P.
ORIGINATOR: SCHMIDT, A.D.
COMPANY NAME: FLA PWR & LIGHT
SUBJECT:

DOC DATE: 781101
ACCESSION NBR: 7811080148
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+1

LER#78-014/03L-0 on 781002: Condensate storage Tank (CST) fell to 182,000 gallons because of water demand increase for steam generator blowdown resulting from cation resin bed regeneration. CST filled after resin bed regeneration.

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

TOTAL NUMBER OF COPIES REQUIRED:
LTR
ENCL

42
42

NOTES:

1973

A104
cep



November 1, 1978

PRN-LI-78-312

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-78-14
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: OCTOBER 2, 1978

TECHNICAL SPECIFICATION 3.8.1.c
CONDENSATE STORAGE TANK

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30-day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Robert Lowenstein, Esquire
Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)

REGULATORY BOARD FILE COPY

A002
3/11

781108 0148

PEOPLE ... SERVING PEOPLE