

REGULATORY DIVISION



December 22, 1978  
L-78-397

Director of Nuclear Reactor Regulation  
Attention: Mr. Victor Stello, Director  
Division of Operating Reactors  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555.

Dear Mr. Stello:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Proposed Amendment to Facility  
Operating Licenses DPR-31 and DPR-41

In accordance with 10 CFR 50.30, Florida Power & Light Company submits herewith three (3) signed originals and forty (40) copies of a request to amend Appendix A of Facility Operating Licenses DPR-31 and DPR-41.

The subject proposal requests changes in the rod insertion limits for both Units 3 and 4. The purpose of the changes is to allow more flexibility in the long range reload planning for the Turkey Point units. We intend to incorporate the revised rod insertion limits for Unit 4, Cycle 6, which is scheduled to begin in May, 1979. Therefore, we request your timely review and approval of our request.

The proposed amendment is described below and shown on the attached Technical Specification pages bearing the date of this letter in the lower right hand corner.

Figures 3.2-1, 1(a), 1(b); & 1(c)

These four figures give the new two and three loop Control Group Insertion Limits for Turkey Point Units 3 and 4.

The proposed amendment has been reviewed by the Turkey Point Plant Nuclear Safety Committee and the Florida Power & Light Company Nuclear Review Board. They have concluded that it does not involve an unreviewed safety question.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

REU/MAS/cf  
Attachment

cc: Mr. James P. O'Reilly, Region II  
Robert Lowenstein, Esquire

781227022/7

Approved  
12/23/78  
3/3  
P

UNIT 4  
CONTROL GROUP INSERTION LIMITS  
FOR THREE LOOP OPERATION




FIGURE 3.2-1

UNIT 4

CONTROL GROUP INSERTION LIMITS  
FOR TWO LOOP OPERATION




FIGURE 3.2-1(a)

UNIT 3  
CONTROL GROUP INSERTION LIMITS  
FOR THREE LOOP OPERATION




FIGURE 3.2-1(b)

UNIT 3  
CONTROL GROUP INSERTION LIMITS  
FOR TWO LOOP OPERATION




FIGURE 3.2-1(c)