

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:7908280681 DOC DATE: 79/08/20 NOTARIZED: NO DOCKET #
 FACIL:50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH.NAME AUTHOR AFFILIATION
 UHRIG,R.E. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 SCHWENCER,A. Operating Reactors Branch 1

SUBJECT: Discusses 790509 reactor vessel loose parts insp.No loose parts observed.Insp rept withheld (ref 10CFR2.790).

DISTRIBUTION CODE: A001S COPIES RECEIVED:LTTR 3 ENCL 0 SIZE: L
 TITLE: GENERAL DISTRIBUTION FOR AFTER ISSUANCE OF OPERATING LIC


NOTES:


	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	05 BC ORB #1	7		
INTERNAL:	01 REG FILE	1	02 NRC PDR	1
	12 I&E	2	14 TA/EDO	1
	15 CORE PERF BR	1	17 ENGR BR	1
	18 REAC SFTY BR	1	19 PLANT SYS BR	1
	20 EEB	1	21 EFLT TRT SYS	1
	22 BRINKMAN	1	OELD	1
EXTERNAL:	03 LPDR	1	04 NSIC	1
	23 ACRS	16		

AUG 30 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR 38 ENCL 0

MA4





August 20, 1979
L-79-229

Office of Nuclear Reactor Regulation
Attention: Mr. A. Schwencer, Chief
Operating Reactors Branch #1
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Schwencer:

Re: Turkey Point Unit 4
Docket No. 50-251
Reactor Vessel Loose Parts Inspection

In accordance with a previous NRC commitment, a Turkey Point Unit 4 reactor vessel loose parts inspection was completed by our NSSS vendor on May 9, 1979. No loose parts were observed. Since the inspection report is a vendor proprietary document it is not being forwarded with this letter; however, it is on file at the Turkey Point Plant for review by Region II inspectors.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/paf

cc: J. P. O'Reilly, Region II
Robert Lowenstein, Esquire

REGULATORY DOCKET FILE COPY

7908280681 :

A001
5/10