


USN REGION
ATLANTA, GEORGIA

79 SEP 12 A 9:10



September 7, 1979
L-79-247

Central File
50-260
261

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-250, 50-251
IE Bulletin 79-03

A list of Turkey Point systems containing longitudinally seam welded piping supplied by Youngstown Welding and Engineering Company has been developed by our Architect/Engineer. The list includes both safety and non-safety systems, and is being reviewed to identify the safety systems. Once the affected safety systems are identified, the inspection program outlined in our letter of June 5, 1979 (L-79-154) will be developed. The next status report will be issued about October 15, 1979.

Very truly yours,

Robert E. Uhrig

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/cph

cc: Office of Inspection & Enforcement, Division of Reactor
Construction Inspection
Robert Lowenstein, Esquire

790676
OFFICIAL COPY
PEOPLE...SERVING PEOPLE

7910040 639

KB
Adz
6