

USNRC REGION II
ATLANTA, GEORGIA

79 SEP 26 All : 05

Central file
BOX 529100, MIAMI, FL 33152



September 24, 1979
L-79-269

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-250, 50-251
IE Bulletin 79-18

We have reviewed the subject Bulletin and a response for Turkey Point
Units 3 and 4 is attached.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/cph

Attachment

cc: Office of Inspection and Enforcement, Division of
Reactor Operations Inspection
Robert Lowenstein, Esquire

7910090669

cf
PO2
Q
OFFICIAL COPY.
PEOPLE...SERVING PEOPLE

ATTACHMENT

Re: RII:JPO
50-250, 50-251
IE Bulletin 79-18

We have reviewed the in situ configuration and performance of the Turkey Point site communications network. The evaluation consisted of a review of:

1. Preoperational Procedure T9800.1, "Functional Test of Communication Systems"
2. Noise Surveys of Turkey Point Unit Nos. 3 & 4 performed to determine areas requiring hearing protection
3. Critiques of Emergency Drills
4. The Emergency Plan and implementing procedures
 - EP 20109 Local Evacuation and Personnel Accountability
 - EP 20110 Owner Controlled Area Evacuation
 - EP 20112 Communications Network
 - EP 20113 Emergency Procedure Drills and Alarm Tests

Our review has identified plant areas where the audibility of the Public Address (PA) portion of the communication system may be improved. As such, a Plant Change/Modification has been prepared and is being implemented. Completion is scheduled for November 1979.

We feel that the above modification will ensure that alarm systems and evacuation announcements are clearly audible throughout all plant areas. Additional assurance is provided via existing administrative and procedural controls.